

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS21007641/KTF3E2

Date: 10/09/2021

REFERENCE

Insured/Claimant: TAN BENG JIN BENJAMIN Policy No: MPC21B00005800
Date of Loss: 13/07/2021 Nature of Claim: OD Claim No: DMPC2100224H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV3594M**
Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ117565
Reg. Date: 30/04/2018 (Man. Year: 2018) Chassis No: JTEZB3GH80J001904
Colour: Metallic Pearl White Odometer: 61730 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,984.00	4,958.25	1,025.75	17.14
Miscellaneous Items	45.00	45.00	0.00	0.00
Labour	2,230.00	1,500.00	730.00	32.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,259.00	6,503.25	1,755.75	21.26
- Excess (S\$)	500.00	0.00	500.00	100.00
(S\$)	7,759.00	6,503.25	1,255.75	16.18
+ GST 7.00/7.00% (S\$)	543.14	455.23	87.91	16.19
Nett Amount (S\$)	8,302.14	6,958.48	1,343.66	16.18

INSPECTION

Date of Assignment: 14/07/2021 Present Location: Ricardo Auto Centre Pte Ltd (HQ)
Date Inspected: 15/07/2021 Inspected At: Ricardo Auto Centre Pte Ltd (HQ)
160 Sin Ming Drive, #02-02, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2021)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV3594M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cracked	260.00 F	*260.00 F
2	1		*FRONT BUMPER SPONGE (WCP)	Cracked	45.00 F	*45.00 F
3	1		*FRONT BUMPER REINFORCEMENT (WCP)	Repair	130.00 F	*- F
4	2		*FRONT BUMPER RETAINER LH & RH (WCP)	Distorted	70.00 F	*70.00 F
5	1		*FRONT BUMPER RETAINER LOWER GRILLE (WCP)	Cracked	180.00 F	*180.00 F
6	10		*FRONT BUMPER CLIPS (WCP)	Necessary	25.00 F	*12.50 F
7	1		*FRONT BUMPER CLIMATE SENSOR RH (WCP)	Shorted	150.00 F	*65.00 F
8	1		*FRONT BUMPER CLIMATE COVER RH (WCP)	Serviceable	20.00 F	*- F
9	1		*FRONT FENDER LH (WCP)	Buckled	280.00 F	*280.00 F
10	1		*HEADLAMP LH (WCP)	Mtg Cracked	1,980.00 F	*1,980.00 F
11	1		*FRONT SUPPORT PANEL (WCP)	Repair	295.00 F	*- F
12	1		*FRONT APRON PANEL (WCP)	Bent	95.00 F	*95.00 F
13	1		*FRONT BUMPER LID (WCP)	Distorted / Cracked	120.00 F	*120.00 F
14	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	550.00 F	*550.00 F
15	10		*RADIATOR TOP COVER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
<u>Supplementary #1</u>						
16	1		*FOG LAMP LH (WCP)	Mtg Cracked	90.00 F	*90.00 F
17	1		*FRONT BUMPER LOWER MOULDING (WCP)	Dented	140.00 F	*140.00 F
18	1		*FRONT SUPPORT UPPER REINFORCEMENT (WCP)	Bent	95.00 F	*95.00 F
19	1		*FRONT BUMPER SPONGE LH SIDE (WCP)	Cracked	25.00 F	*25.00 F
20	1		*FRONT BUMPER SPONGE RH SIDE (WCP)	Cracked	25.00 F	*25.00 F
21	1		*FRONT GRILLE ASSY (WCP)	Cracked	340.00 F	*340.00 F
22	1		*FRONT BUMPER SPONGE LH SIDE (WCP)	Repeated	25.00 F	*- F
23	1		*FRONT BUMPER SPONGE RH SIDE (WCP)	Repeated	25.00 F	*- F
24	1		*GRILLE SUB ASSY (WCP)	Repeated	340.00 F	*- F
<u>Supplementary #2</u>						
25	1		*RADIATOR TOP COVER (WCP)	Cracked	120.00 F	*120.00 F

F=Franchise part.

Sub Total (\$\$) **5,440.00** **4,507.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	SUPPLY & REPLACE FRONT NUMBER PLATE WITH HOLDER (BENT)	45.00	45.00
Sub Total (\$\$)			45.00	45.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT, WELD & STRAIGHTEN FRONT PORTION OF CAR CAUSED BY ACCIDENT. ADJUST & REPLACE DAMAGE PARTS.	New	900.00	500.00
2	TO FOCUS HEADLAMP	New	30.00	20.00
3	TO CHECK AIRCON SYSTEM, REMOVE & REPLACE AIRCON CONDENSER, RECHARGE SYSTEM.	New	120.00	100.00
4	TO SPRAY PAINT REPAIRED AREAS.	New	1,000.00	800.00
5	TO RE-PROGRAM CLIMATE SENSOR SYSTEM	New	180.00	80.00
Gross Labour Cost (\$\$)			2,230.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >