

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/GRB21007643/KBS3Q2
Date: 27/08/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMU4394Y	Insured Vehicle No :	SLP8772B
Date of Loss:	10/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU4394Y		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Engine No:	1ZRX591597
Reg. Date:	05/05/2017 (Man. Year: 2016)	Chassis No:	MR053REH104557094
Colour:	Metallic Black	Odometer:	103096 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,036.85	3,705.50	3,331.35	47.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,120.00	810.00	41.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,966.85	4,825.50	4,141.35	46.19
Approved Total (Overridden) (S\$)		3,800.00		

(S\$)	8,966.85	3,800.00	5,166.85	57.62
+ GST 7.00/7.00% (S\$)	627.68	266.00	361.68	57.62
Nett Amount (S\$)	9,594.53	4,066.00	5,528.53	57.62
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 15/07/2021

Inspected At:

Bodyfix (HQ)

10 Ang Mo Kio Industrial Park 2, #04-06, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Aug 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU4394Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent / Cracked	581.45 F	*581.45 F
2	1		*FRONT BUMPER REINFORCEMENT	Repair	350.50 F	*- F
3	1		*FRONT SUPPORT PANEL	*Check	450.80 F	*- F
4	1		*HEAD LAMP (LH)	Mtg Cracked	1,218.45 F	*1,218.45 F
5	1		*HEAD LAMP (RH)	Cracked	1,218.45 F	*1,218.45 F
6	1		*FRONT GRILLE	Mtg Cracked	330.50 F	*330.50 F
7	1		*LOGO	Necessary	52.15 F	*52.15 F
8	1		*BONNET	Repair	972.25 F	*- F
9	1		*BONNET HINGE -RH	Repair	157.20 F	*- F
10	1		*BONNET HINGE -LH	Repair	157.20 F	*- F
11	1		*FRONT FENDER (RH)	Repair	591.60 F	*- F
12	1		*FOG LAM (FRONT LH)	Serviceable	220.30 F	*- F
13	1		*FOG LAM (FRONT RH)	*Check	220.30 F	*- F
14	1		*FOG LAMP COVER LH	Serviceable	105.60 F	*- F
15	1		*FOG LAMP COVER RH	*Check	105.60 F	*- F
16	2		*FRONT BUMPER SIDE RETAINER	Distorted	264.50 F	*264.50 F
17	1		*FRONT NO PLATE	Cracked	40.00 FS	*40.00 FS
					Total Parts (\$\$)	7,036.85
						3,705.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK & TEST LIGHTING FUNCTIONS	New	80.00	20.00
2	RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS	New	100.00	0.00
3	LABOUR TO REPLACE ABOVE PARTS ,PANEL BEAT ,REPAIR & REALIGN DAMAGE PARTS	New	850.00	500.00
4	SPRAY PAINT FRONT BUMPER ,FRONT FENDER RIGHT AND OTHER AFFECTED AREAS	New	900.00	600.00
Gross Labour Cost (\$\$)			1,930.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >