



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 9111Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER BRACKET RH	NOT NECESSARY	25.00	-
1	REINFORCEMENT BAR	NOT NECESSARY	384.00	-
1	REAR BUMPER LOWER REFLECTOR RH	NOT NECESSARY	28.00	-
1	REAR TAILLAMP RH	NOT NECESSARY	520.00	-
	LESS 10% DISCOUNT		-95.70	-
			861.30	-
1	REAR BUMPER	CUT	720.00	580.30
	LESS 10% DISCOUNT		-72.00	-
	LESS 20% DISCOUNT		-	-116.06
			648.00	464.24
	<b><u>SPECIAL NETT ITEMS</u></b>			
4	REAR BUMPER CLIP (SN)	NECESSARY	8.00	8.00
			8.00	8.00
	<b><u>LABOUR</u></b>			
	TO REMOVE AND RENEW REAR DAMAGED PARTS, REPLACE REALIGNED ALL AFFECTED PARTS.		500.00	200.00
	TO RESPRAY AFFECTED AREAS.		250.00	200.00
	TO REMOVE/REFIX WIRING CHECKS.	NOT NECESSARY	120.00	-
	TO TUFFCOAT AFFECTED AREA.	NOT NECESSARY	100.00	-
			970.00	400.00
	<b>GRAND TOTAL</b>		<b>2,487.30</b>	<b>872.24</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>700.00</b>

Report Ref No. CS/SMR21007646/Guf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.