

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21007647/APS3Q2

Date:

18/10/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D19MFL0005549_01

Claimant Vehicle No : GBJ3356C**Insured Vehicle No :**

GBK1761Z

Date of Loss: 13/07/2021

Nature of Claim:

TP

Claim No:

MFL2021D0002955

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBJ3356C**

Make & Model: ISUZU TFR87JDR, 1.9 D D/CAB (A)

Engine No:

TE5330

Reg. Date: 20/03/2019 (Man. Year: 2018)

Chassis No:

MPATFS87JJT012088

Colour: Silver

Odometer:

123620 km

Engine Capacity: 1898 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/70 R16

Rear Tyre Size:

245/70 R16

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,587.65	3,607.00	1,980.65	35.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,590.00	920.00	36.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,097.65	5,197.00	2,900.65	35.82
+ GST 7.00/7.00% (S\$)	566.84	363.79	203.05	35.82

Nett Amount (S\$)	8,664.49	5,560.79	3,103.70	35.82
+ Loss of Use (9.0 x S\$80.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,317.24		
Global Sum Settlement (S\$)		6,250.00		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 15/07/2021

Estimated Period of Repair: 6.0 days

Inspected At: Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Sep 2021)	
Parts:	N/A	ISUZU TFR87JDR 1.9 D D/CAB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ3356C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,170.00 FL	*924.00 FL
2	1		*REAR BUMPER TOP GARNISH RUBBER	Deformed	428.00 FL	*428.00 FL
3	2		*REAR BUMPER BRACKET	Bent	345.60 FL	*345.60 FL
4	1		*REAR TAIL-GATE	Dented	1,370.00 FL	*1,058.00 FL
5	1		*REAR TAIL-GATE LOCK	Not Necessary	156.80 FL	*- FL
6	1		*REAR TAIL-GATE HANDLE	Not Necessary	148.00 FL	*- FL
7	1		*REAR TAIL-GATE HINGES	Bent	160.00 FL	*160.00 FL
8	1		*REAR TAIL-GATE HINGES PIN	Bent	60.00 FL	*60.00 FL
9	1		*REAR N/S TAIL LAMP	Cracked	435.60 FL	*365.00 FL
10	1		*REAR TAIL-GATE 70KMPH EMBLEM	Necessary	15.00 FS	*15.00 FS
11	1		*REAR TAIL-GATE 6 PAX EMBLEM	Necessary	15.00 FS	*15.00 FS
12	1		*REAR TAIL-GATE ISUZU EMBLEM	Necessary	68.00 FS	*68.00 FS
13	1		*REAR TAIL-GATE D-MAX EMBLEM	Necessary	68.90 FS	*68.90 FS
14	1		*REAR END PANEL	Dented	465.40 FL	*465.40 FL
15	1		*REAR REG NO.PLATE	Bent	25.00 FS	*25.00 FS
16	1		*REAR N/S FENDER	Repair	1,255.60 FL	*- FL
17	1		*REAR N/S FENDER BODY STICKER	Necessary	300.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,486.90	4,177.90
- List Item Discount on L Items 15.00/15.00% (\$\$)	899.25	570.90
Total Parts (\$\$)	5,587.65	3,607.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE ,WELDING ,KNOCKING AND REPLACE REAR DAMAGE PARTS	New	1,400.00	800.00
2	TO SPRAY PAINTING	New	1,000.00	700.00
3	TO RE-SEAL ANTI RUST	New	60.00	60.00
4	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (\$\$)			2,510.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >