

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21007649/R1BA3Q2  
**Date:** 06/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MPC0002932
<b>Claimant Vehicle No :</b>	SMJ3031J	<b>Insured Vehicle No :</b>	SMX5661D
Date of Loss:	30/06/2021	Nature of Claim:	TP
		Claim No:	MPC2021D0002921

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMJ3031J</b>		
Make & Model:	BMW X3 XDRIVE30I, 2.0 LED NAV HUD MSPT (A)	Engine No:	F3393211B48B20B
Reg. Date:	28/02/2019 (Man. Year: 2018)	Chassis No:	WBATR92050LE26558
Colour:	Blue	Odometer:	45003 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	275/40 R20	Rear Tyre Size:	275/40 R20
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,153.00	2,178.05	974.95	30.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	2,004.00	486.00	19.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,643.00</b>	<b>4,182.05</b>	<b>1,460.95</b>	<b>25.89</b>
<b>+ GST 7.00/7.00% (S\$)</b>	395.01	292.74	102.27	25.89

<b>Nett Amount (S\$)</b>	<b>6,038.01</b>	<b>4,474.79</b>	<b>1,563.22</b>	<b>25.89</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,782.24</b>		

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 15/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Performance Motors Limited (Alexandra)  
 303 Alexandra Road, Sime Darby Performance Centre  
 Singapore 159941

**Adjuster:** MOHD RASUL**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Sep 2021)
<b>Parts:</b>	M1-SUV	BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMJ3031J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*SUNDRIES</b>	Necessary	150.00 FS	*80.00 FS
2	1		<b>*REAR BUMPER CARRIER</b>	Serviceable	765.35 FS	*- FS
3	1		<b>*RH SIDE GUIDE FOR BUMPER</b>	Serviceable	58.55 FS	*- FS
4	1		<b>*REAR BUMPER BOTTOM REINFORCEMENT</b>	Cracked	79.25 FS	*76.87 FS
5	1		<b>*REAR BUMPER PANEL PRIMED (M/PMA)</b>	Deformed	1,563.20 FS	*1,516.30 FS
6	1		<b>*REAR BUMPER BOTTOM TRIM PANEL (M)</b>	Cracked	372.20 FS	*361.03 FS
7	4		<b>*DECOUPING RING PDC TORQUE CONVERTER</b>	Not Necessary	20.60 FS	*- FS
8	1		<b>*LH SIDE GUIDE FOR BUMPER</b>	Cracked	130.27 FS	*130.27 FS
9	1		<b>*EXPANDING RIVET BLACK</b> (10 PCS)	Necessary	13.58 FS	*13.58 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>3,153.00</b>	<b>2,178.05</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER PANEL AND ATTACHMENTS	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
Gross Labour Cost (\$\$)			2,490.00	2,004.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >