

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007653/KPA3Q2
Date: 29/10/2021**REFERENCE**

| | | | |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D21MCV0002353 |
| Claimant Vehicle No : | SGR2158M | Insured Vehicle No : | GBD71A |
| Date of Loss: | 12/07/2021 | Nature of Claim: | TP |
| | | Claim No: | MCV2021D0002982 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No: | SGR2158M | | |
| Make & Model: | TOYOTA PICNIC, 2.0 W/O ROOF RACK (A) | Engine No: | 1AZ5542627 |
| Reg. Date: | 02/02/2007 (Man. Year: 2006) | Chassis No: | JTEGH23B900023045 |
| Colour: | Metallic Black | Odometer: | 262155 km |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|----------------|
| Front Tyre Size: | 205/60 R16 | Rear Tyre Size: | 205/60 R16 |
| Front Left Side: | Aeolus 7 mm | Rear Left Side: | West Lake 3 mm |
| Front Right Side: | Aeolus 7 mm | Rear Right Side: | West Lake 3 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,393.73 | 4,246.45 | 1,147.28 | 21.27 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,940.00 | 1,530.00 | 410.00 | 21.13 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 7,333.73 | 5,776.45 | 1,557.28 | 21.23 |
| Approved Total (Overridden) (S\$) | | 4,600.00 | | |

| | | | | |
|---|-----------------|-----------------|-----------------|--------------|
| (S\$) | 7,333.73 | 4,600.00 | 2,733.73 | 37.28 |
| + GST 7.00/7.00% (S\$) | 513.36 | 322.00 | 191.36 | 37.28 |
| Nett Amount (S\$) | 7,847.09 | 4,922.00 | 2,925.09 | 37.28 |
| + Car Rental (8.0 x S\$100.00/day) (S\$) | | 800.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 5,729.45 | | |

INSPECTION

Date of Assignment: 14/07/2021

Date Inspected: 16/07/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 21 Sep 2021) |
| Parts: | M1-MPV | TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGR2158M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|--------------------|-------------|--------------|
| 1 | 1 | | *TAIL GATE | Bent | 1,306.90 FL | *1,306.90 FL |
| 2 | 1 | | *TAIL GATE GLASS MOULDING | Necessary | 155.30 FL | *155.30 FL |
| 3 | 1 | | *TAIL GATE RUBBER (50%) | Dented / Distorted | 185.63 FS | *123.75 FS |
| 4 | 1 | | *TAIL GATE INNER TRIM COVER | Dented | 423.30 FL | *423.30 FL |
| 5 | 1 | | *TAIL GATE INNER LOCK | Dented | 217.40 FL | *217.40 FL |
| 6 | 1 | | *TAIL GATE WIPER MOTOR | Bent / Jammed | 566.40 FL | *566.40 FL |
| 7 | 1 | | *TAIL GATE LOGO | Necessary | 70.90 FL | *70.90 FL |
| 8 | 1 | | *TAIL GATE TOYOTA EMBLEM | Necessary | 41.40 FL | *41.40 FL |
| 9 | 1 | | *TAIL GATE PICNIC EMBLEM | Necessary | 48.40 FL | *48.40 FL |
| 10 | 1 | | *TAIL GATE OUTER GARNISH | Warped | 99.70 FL | *99.70 FL |
| 11 | 2 | | *TAIL GATE LAMP | Serviceable | 512.60 FL | *- FL |
| 12 | 2 | | *TAIL GATE LICENSE PLATE LAMP | Cracked | 85.80 FL | *85.80 FL |
| 13 | 1 | | *REAR END PANEL | Bent | 416.10 FL | *416.10 FL |
| 14 | 1 | | *END PANEL TOP GARNISH | Mtg Distorted | 206.20 FL | *206.20 FL |
| 15 | 1 | | *REAR FENDER INNER TRIM COVER | O/S Cracked | 1,572.80 FL | *786.40 FL |
| 16 | 1 | | *REAR BUMPER FASCIA | Buckled | 511.20 FL | *511.20 FL |
| 17 | 1 | | *REAR BUMPER SIDE RETAINER | O/S Distorted | 96.40 FL | *48.20 FL |
| 18 | 1 | | *REAR BUMPER REVERSE SENSOR (3 PCS) | Dented / Cracked | 350.00 FS | *300.00 FS |
| 19 | 1 | | *REAR W/S GLASS SEALANT | Necessary | 60.00 FS | *40.00 FS |
| 20 | 1 | | *REAR NO. PLATE WITH BOX | Dented | 50.00 FS | *45.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 6,976.43 | 5,492.35 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 1,582.70 | 1,245.90 |
| Total Parts (\$\$) | 5,393.73 | 4,246.45 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST | New | 150.00 | 120.00 |
| 2 | TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET | New | 120.00 | 100.00 |
| 3 | TO REMOVE AIR CON CONDENSER ,PIPES AND DRIER ,VACUUM AND TO RECHARGE GAS | New | 120.00 | 0.00 |
| 4 | TO APPLY UNDERSEALING | New | 100.00 | 60.00 |
| 5 | TO PUTTY AND SPRAY REPLACED PARTS | New | 750.00 | 650.00 |
| 6 | TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS | New | 700.00 | 600.00 |
| Gross Labour Cost (S\$) | | | 1,940.00 | 1,530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >