

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007655/AVCE2

Date: 01/11/2021

REFERENCE

Insured/Claimant:	KUROFUCHI YUTAKA	Policy No:	7210018297		
Date of Loss:	09/07/2021	Nature of Claim:	OD	Claim No:	3327494293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCL579Z		
Make & Model:	AUDI A6, 3.0 TFSI quattro S-Line (C6) (A)	Engine No:	CRE026367
Reg. Date:	01/04/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ4G6FN053609
Colour:	Grey	Odometer:	80303 km
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$106,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,270.00	6,633.84	6,636.16	50.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,464.00	5,872.00	4,592.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,734.00	12,505.84	11,228.16	47.31
- Excess (S\$)	250.00	250.00	0.00	0.00
(S\$)	23,484.00	12,255.84	11,228.16	47.81
+ GST 7.00/7.00% (S\$)	1,643.88	857.91	785.97	47.81
Nett Amount (S\$)	25,127.88	13,113.75	12,014.13	47.81

INSPECTION

Date of Assignment:	15/07/2021		
Date Inspected:	13/07/2021	Inspected At:	24 BENOI SECTOR Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	9.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	3,268.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	273.00 FS	*- FS
3	1		*REAR BUMPER CLOSING ELEMENT - RH	Not Necessary	81.00 FS	*- FS
4	1		*REAR BUMPER SECURING STRIP	Not Necessary	223.00 FS	*- FS
5	1		*REAR BUMPER LOWER GUIDE SECTION - RH	Not Necessary	53.00 FS	*- FS
6	2		*REAR BUMPER GUIDE SECTION SUPPORT - LH / RH	Not Necessary	66.00 FS	*- FS
7	1		*REAR BUMPER BRACKET - RH	Not Necessary	67.00 FS	*- FS
8	2		*REAR BUMPER HOLDING STRIP - LH / RH	Not Necessary	126.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	106.00 FS	*- FS
10	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	3.00 FS	*- FS
12	1		*REAR WHEEL HOUSING LINER RH	Not Necessary	275.00 FS	*- FS
13	1		*ATTACHMENT PARTS FOR REAR WHEEL HOUSING LINER	Not Necessary	73.00 FS	*- FS
14	1		*REAR ALUMINIUM RIM - RH	Cut	1,955.00 FS	*1,564.00 FS
15	1		*REAR WHEEL BEARING - RH	Bent	1,097.00 FS	*877.60 FS
16	1		*SUSPENSION CONTROL ARM - LOWER RH	Bent	905.00 FS	*724.00 FS
17	1		*REAR CONTROL ARM - RH	Bent	115.00 FS	*92.00 FS
18	1		*SUSPENSION CONTROL ARM - UPPER RH	Bent	593.00 FS	*474.40 FS
19	1		*SIDE MEMBER TRIM ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
20	1		*SIDE MEMBER TRIM ADHESIVE TAPE	Not Necessary	16.00 FS	*- FS
21	1		*DOUBLE SIDE ADHESIVE TAPE (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*STONE GUARD - RH FRONT	Not Necessary	118.00 FS	*- FS
23	1		*SUNDRIES	Necessary	400.00 FS	*207.44 FS
24	1		*REAR SUB-FRAME (Supplementary)	Bent	3,368.00 FS	*2,694.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 13,270.00 6,633.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	750.00
3	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL TRIM AND RHS REAR DOOR	New	4,000.00	1,650.00
4	TO REMOVE AND RENEW RHS REAR WHEEL SUSPENSION ASSY	New	2,400.00	2,400.00
5	TO RENEW RHS REAR RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
6	TO CARRY PRE/POST OUT DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			10,464.00	5,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >