

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007656/ATCN2**Date:** 12/10/2021**REFERENCE**

| | | | | |
|-------------------|-------------|------------------|------------|------------------------|
| Insured/Claimant: | IKSAN KARIM | Policy No: | 2100265115 | |
| Date of Loss: | 11/07/2021 | Nature of Claim: | OD | Claim No: 5804498827SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SDH8232E | | |
| Make & Model: | AUDI A8 L, 3.0 TFSI QU (A) | Engine No: | CGW004294 |
| Reg. Date: | 16/06/2011 (Man. Year: 2010) | Chassis No: | WAUZZZ4H5BN010527 |
| Colour: | Black | Odometer: | 41839 km |
| Engine Capacity: | 2995 cc | | |
| Market Value/New Car Price: | S\$56,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 255/45R19 | Rear Tyre Size: | 255/45R19 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 25,232.00 | 10,211.60 | 15,020.40 | 59.53 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 11,314.00 | 3,372.00 | 7,942.00 | 70.20 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 36,546.00 | 13,583.60 | 22,962.40 | 62.83 |
| - Excess (S\$) | 1,400.00 | 1,400.00 | 0.00 | 0.00 |
| (S\$) | 35,146.00 | 12,183.60 | 22,962.40 | 65.33 |
| + GST 7.00/7.00% (S\$) | 2,460.22 | 852.85 | 1,607.37 | 65.33 |
| Nett Amount (S\$) | 37,606.22 | 13,036.45 | 24,569.77 | 65.33 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 15/07/2021 | |
| Date Inspected: | 13/07/2021 | Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 6.0 days | |

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 3,649.00 FS | *2,919.20 FS |
| 2 | 1 | | *FRONT BUMPER CLOSING ELEMENT-LOWER CENTER | Not Necessary | 262.00 FS | *- FS |
| 3 | 1 | | *FRONT BUMPER SPOILER | Not Necessary | 297.00 FS | *- FS |
| 4 | 2 | | *FRONT WHEEL SPOILER-LH OUTER/INNER | Not Necessary | 81.00 FS | *- FS |
| 5 | 1 | | *FRONT BUMPER FOAM FILLER PIECE | Not Necessary | 127.00 FS | *- FS |
| 6 | 1 | | *FRONT BUMPER CARRIER | Not Necessary | 1,157.00 FS | *- FS |
| 7 | 1 | | *FRONT BUMPER CARRIER COVER | Not Necessary | 65.00 FS | *- FS |
| 8 | 2 | | *FRONT BUMPER RETAINING BRACKET-LH/RH | Not Necessary | 30.00 FS | *- FS |
| 9 | 1 | | *FRONT BUMPER GUIDE PIECE-LH | Damaged | 53.00 FS | *41.68 FS |
| 10 | 1 | | *FRONT BUMPERTOP COVER | Not Necessary | 127.00 FS | *- FS |
| 11 | 1 | | *CAUTION STICKER | Not Necessary | 14.00 FS | *- FS |
| 12 | 1 | | *A/C STICKER | Not Necessary | 30.00 FS | *- FS |
| 13 | 1 | | *FRONT BUMPER GRILLE-LH | Missing | 421.00 FS | *336.40 FS |
| 14 | 2 | | *HORN-LOW/HIGH TONE | Not Necessary | 483.00 FS | *- FS |
| 15 | 1 | | *HORN BRACKET | Not Necessary | 128.00 FS | *- FS |
| 16 | 1 | | *FRONT BUMPER SENSOR | Not Necessary | 0.00 FS | *- FS |
| | | | NPA | | | |
| 17 | 4 | | *FRONT BUMPER SENSOR SEAL RING | Not Necessary | 6.00 FS | *- FS |
| 18 | 1 | | *FRONT RADIATOR GRILLE | Not Necessary | 1,918.00 FS | *- FS |
| 19 | 1 | | *FRONT RADIATOR GRILLE STRIKER PLATE-UPPER | Cracked | 131.00 FS | *104.80 FS |
| 20 | 1 | | *FRONT RADIATOR GRILLE REINFORCEMENT-LH | Damaged | 49.00 FS | *38.80 FS |
| 21 | 1 | | *FRONT FENDER-LH | Dented | 1,842.00 FS | *1,473.60 FS |
| 22 | 1 | | *FRONT FENDER ATTACHMENT PARTS | Not Necessary | 287.00 FS | *- FS |
| 23 | 1 | | *FRONT FENDER BRACKET-LH | Not Necessary | 34.00 FS | *- FS |
| 24 | 1 | | *FRONT FENDER BRACE-LH | Bent | 850.00 FS | *680.00 FS |
| 25 | 1 | | *FRONT FENDER BRACKET-FRONT LH | Damaged | 25.00 FS | *19.84 FS |
| 26 | 1 | | *FRONT FENDER CONNECTING PIECE | Damaged | 243.00 FS | *194.00 FS |
| 27 | 1 | | *FRONT BUMPER RETAINING BRACKET-LH | Damaged | 18.00 FS | *13.76 FS |
| 28 | 1 | | *FRONT WHEEL HOUSING LINER-LH FRONT | Not Necessary | 296.00 FS | *- FS |
| 29 | 1 | | *FRONT WHEEL HOUSING LINER-LH REAR | Not Necessary | 221.00 FS | *- FS |
| 30 | 1 | | *FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 197.00 FS | *- FS |
| 31 | 1 | | *FRONT HEADLIGHT-LH | Cracked | 5,107.00 FS | *4,085.60 FS |
| 32 | 1 | | *FRONT HEADLIGHT CONTROL UNIT | Not Necessary | 1,116.00 FS | *- FS |
| 33 | 1 | | *FRONT HEADLIGHT GAS DISCHARGE LAMP | Not Necessary | 416.00 FS | *- FS |
| 34 | 1 | | *FRONT HEADLIGHT LIFT CYLINDER-LH | Damaged | 274.00 FS | *219.20 FS |
| 35 | 1 | | *FRONT HEADLIGHT LIFT CYLINDER HOSE | Not Necessary | 109.00 FS | *- FS |
| 36 | 1 | | *FRONT LOCK CARRIER | Not Necessary | 1,131.00 FS | *- FS |
| 37 | 12 | | *BOLTS | Not Necessary | 117.00 FS | *- FS |
| 38 | 1 | | *FRONT BUMPER SIDE MEMBER-LH | Not Necessary | 196.00 FS | *- FS |
| 39 | 1 | | *FRONT ADDITIONAL COOLER-LH | Not Necessary | 807.00 FS | *- FS |
| 40 | 1 | | *FRONT ADDITIONAL COOLER BRACKET-LH | Not Necessary | 157.00 FS | *- FS |
| 41 | 1 | | *FRONT ADDITIONAL COOLER PUMP BRACKER - LH | Not Necessary | 179.00 FS | *- FS |
| 42 | 1 | | *FRONT COOLANT PUMP | Not Necessary | 1,333.00 FS | *- FS |
| 43 | 1 | | *FRONT COOLANT PUMP HOLDER - LH | Not Necessary | 69.00 FS | *- FS |
| 44 | 1 | | *SOLENOID VALVE | Not Necessary | 347.00 FS | *- FS |
| 45 | 1 | | *STOP BUFFER | Not Necessary | 17.00 FS | *- FS |
| 46 | 1 | | *FRONT ADDITIONAL RADIATOR AIR GUIDE | Not Necessary | 79.00 FS | *- FS |
| 47 | 1 | | *COOLANT | Not Necessary | 142.00 FS | *- FS |
| 48 | 1 | | *FRONT RADAATOR AIR GUIDE | Not Necessary | 88.00 FS | *- FS |
| 49 | 1 | | *FRONT NO. PLATE | Not Necessary | 60.00 FS | *- FS |
| 50 | 1 | | *SUNDRIES | Necessary | 350.00 FS | *7.44 FS |
| 51 | 1 | | *FONR BUMPER LOCKING CLIP | Necessary | 39.00 FS | *31.20 FS |
| | | | Supplementary | | | |
| 52 | 2 | | *HEADLIGHT BRACKET | Cracked | 58.00 FS | *46.08 FS |
| | | | Supplementary | | | |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|-------------|-----------|--------------------------|------------------|
| | | | | | Total Parts (S\$) | 25,232.00 |
| | | | | | | 10,211.60 |
| Report was unsubmitted during this print-out. | | | | | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New | 480.00 | 480.00 |
| 2 | TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 450.00 | 300.00 |
| 3 | TO REMOVE AND REINSTALL AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM TO CARRY OUT VACUUM AND REGAS | New | 2,000.00 | 0.00 |
| 4 | TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.TO RENEW FRONT LOCK CARRIER AND ALIGN POSITION.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | New | 5,400.00 | 1,200.00 |
| 5 | TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER | New | 2,600.00 | 1,200.00 |
| 6 | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK | New | 384.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 11,314.00 | 3,372.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >