

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | | | - | | |
|----|---|---|-------------------------|----------|----------------------------------|--|
| | 4)/4 INIQUE 4NIQE | | ationale Des Experts En | | obile CS3/ASM2100582 | |
| | AXA INSURANCE | | | Ref: | 000/A0M21005021/R1vo | |
| | 8 SHENTON WAY AXA TOWERSING | | | Date: | 14/05/2021 15.07.2021 | |
| | | | | Code: | ASM | |
| | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SKB 298S | Veh. Inspected | | SMN 7660X | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | S1M03A2M | Excess (\$) | | 0.00 | |
| | Assign From | CHONG Arnold | Assign Date | | 44/05/2024 15.07.2021 | |
| | | Vehicle Pa | rticulars & Conditi | on | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| • | | Descri | ption of Damages | | | |
| | | | | | | |
| | General Information | | | | 47/05/0004 | |
| | Accident Date | 13/05/2021 | Inspection Date | <u> </u> | 17/05/2021 | |
| | Survey held at | SENG HWEE MOTOR | | | | |
| | | BLK 1018, #01-350 YISHUN INDUSTRIAL PARK SINGAPORE 768760 | Α | | | |
| a. | | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | | |