

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21007659/ATCE2

Date: 28/10/2021

REFERENCE

Insured/Claimant:	CHANG JIAN XIONG WILLIAM	Policy No:	7210010967	
Date of Loss:	09/07/2021	Nature of Claim:	OD	Claim No: 6993684137SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ1133K	Engine No:	DEM028990
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF50MA018600
Reg. Date:	29/01/2021 (Man. Year: 2020)	Odometer:	7485 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,734.00	8,769.28	11,964.72	57.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,312.00	6,412.00	7,900.00	55.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,046.00	15,181.28	19,864.72	56.68
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	33,446.00	13,581.28	19,864.72	59.39
+ GST 7.00/7.00% (S\$)	2,341.22	950.69	1,390.53	59.39
Nett Amount (S\$)	35,787.22	14,531.97	21,255.25	59.39

INSPECTION

Date of Assignment:	15/07/2021		
Date Inspected:	14/07/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Repair	1,060.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PART	Not Necessary	53.00 FS	*- FS
3	1		*FRONT FENDER POP RIVET	Not Necessary	20.00 FS	*- FS
4	1		*FRONT FENDER CHROME TRIM	Necessary	164.00 FS	*130.80 FS
5	1		*FRONT DOOR - LH	Distorted	3,884.00 FS	*3,107.20 FS
6	1		*FRONT DOOR OUTER DOOR SEAL	Necessary	222.00 FS	*177.60 FS
7	1		*FRONT DOOR BONDING AGENT	Not Necessary	49.00 FS	*- FS
8	1		*FRONT DOOR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
9	1		*FRONT DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
10	1		*FRONT DOOR CATCH - LH	Not Necessary	120.00 FS	*- FS
11	1		*FRONT DOOR CHROME TRIM - LH	Necessary	164.00 FS	*130.80 FS
12	1		*FRONT MIRROR MOUNTING - LH	Cut	1,937.00 FS	*1,549.60 FS
13	1		*FRONT MIRROR CAP - LH	Repair	289.00 FS	*- FS
14	1		*FRONT MIRROR GLASS - LH	Not Necessary	1,229.00 FS	*- FS
15	1		*FRONT DOOR HANDLE COVER - LH	Cut	88.00 FS	*69.92 FS
16	1		*HOUSING FOR DOOR HANDLE	Not Necessary	8.00 FS	*- FS
17	1		*FRONT DOOR HANDLE LIGHT COVER - LH	Damaged	6.00 FS	*4.64 FS
18	1		*REAR DOOR - LH	Dented	3,884.00 FS	*3,107.20 FS
19	1		*REAR DOOR OUTER SEAL	Necessary	222.00 FS	*177.60 FS
20	1		*REAR BONDING AGENT	Not Necessary	49.00 FS	*- FS
21	1		*REAR CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
22	1		*REAR DOOR APPLICATOR	Not Necessary	8.00 FS	*- FS
23	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	173.00 FS	*- FS
24	1		*REAR DOOR CATCH - LH	Not Necessary	120.00 FS	*- FS
25	1		*REAR DOOR TRIM - LH	Not Necessary	869.00 FS	*- FS
26	1		*DOOR ATTACHMENT PARTS	Necessary	130.00 FS	*104.00 FS
27	1		*ADHESIVE TAPES	Necessary	212.00 FS	*169.60 FS
28	1		*REAR BUMPER	Repair	2,451.00 FS	*- FS
29	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	44.00 FS	*- FS
30	1		*REAR ALUMINIUM RIM - LH	Not Necessary	2,290.00 FS	*- FS
31	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	275.00 FS	*- FS
32	1		*REAR WHEEL HOUSING LINER ATTACHEMENT PART	Not Necessary	169.00 FS	*- FS
33	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
34	1		*STONE CHIP GUARD - LH	Cut	51.00 F	*40.32 F
			(Supplementary)			

F=Franchise part. S=SpcNett.

Total Parts (S\$) 20,734.00 8,769.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	0.00
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	360.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
4	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER, LHS REAR DOOR, LHS SILL PANEL TRIM AND REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,000.00	1,750.00
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS REAR FENDER AND REAR BUMPER	New	6,200.00	3,550.00
6	TO RENEW LHS REAR RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,312.00	6,412.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >