

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21007662/DES3Q2
Date: 27/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLD9600X	Insured Vehicle No :	SLG7281E
Date of Loss:	12/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002995

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9600X	Engine No:	L15Z14102249
Make & Model:	HONDA CITY, 1.5 CVT (A)	Chassis No:	MRHGM6660HP000059
Reg. Date:	01/07/2016 (Man. Year: 2016)	Odometer:	53871 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,526.59	4,052.57	11,474.02	73.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,400.00	2,150.00	5,250.00	70.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,926.59	6,202.57	16,724.02	72.95
Approved Total (Overridden) (S\$)		4,900.00		

	(S\$)	22,926.59	4,900.00	18,026.59	78.63
+ GST 7.00/7.00% (S\$)		1,604.86	343.00	1,261.86	78.63
Nett Amount (S\$)		24,531.45	5,243.00	19,288.45	78.63
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)			856.00		
+ Doc/Search Fee (S\$)			36.45		
Nett Liability (S\$)			6,135.45		

INSPECTION

Date of Assignment: 15/07/2021

Date Inspected: 14/07/2021

Estimated Period of Repair: 6.0 days

Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2021)
Parts: 143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLD9600X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent / Dented	1,380.00 FL	*522.50 FL
2	1		*REAR BOOT NO PLATE TOP CHROME	Not Necessary	330.00 FL	*- FL
3	1		*SET REAR BOOT NO PLATE TOP CHROME CLIPS	Not Necessary	20.00 FL	*- FL
4	1		*REAR BOOT HONDA LOGO	Necessary	106.00 FL	*32.50 FL
5	1		*REAR BOOT CITY EMBLEM	Necessary	78.00 FL	*40.00 FL
6	1		*REAR BOOT I-VTEC EMBLEM	Necessary	88.00 FL	*42.00 FL
7	2		*REAR BOOT LAMP LH/RH	Cracked	979.20 FL	*820.80 FL
8	2		*SETS REAR BOOT LAMP CLIPS	Not Necessary	40.00 FL	*- FL
9	1		*REAR BOOT OPEN SWITCH	Not Necessary	285.50 FL	*- FL
10	1		*REAR BOOT INNER LOCK	Damaged	317.10 FL	*105.70 FL
11	1		*REAR BOOT INNER LOCK CABLE	Not Necessary	89.00 FL	*- FL
12	1		*REAR BOOT STRIKER LOCK	Bent	104.00 FL	*50.80 FL
13	1		*REAR BOOT INNER TRIM	Not Necessary	413.92 FL	*- FL
14	1		*SET REAR BOOT INNER TRIM CLIPS	Not Necessary	20.00 FL	*- FL
15	1		*REAR BOOT WEATHERSTRIP RUBBER	Deformed	243.20 FL	*144.20 FL
16	2		*REAR BOOT HINGE LH/RH	Not Necessary	511.96 FL	*- FL
17	1		*SET REAR BOOT RUBBER STOPPERS	Serviceable	120.00 FL	*- FL
18	1		*REAR BUMPER	Dented	898.00 FL	*463.70 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	16.00 FS	*15.00 FS
20	2		*REAR BUMPER SIDE RETAINER LH/RH	Serviceable	115.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR LH/RH	Not Necessary	389.16 FL	*- FL
22	1		*REAR END PANEL	Buckled	782.49 FL	*481.20 FL
23	1		*REAR END PANEL TOP GARNISH	Deformed / Mtg Cracked	342.84 FL	*199.50 FL
24	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	16.00 FS	*15.00 FS
25	2		*REAR FENDER LH/RH	O/S Not Necessary / N/S Repair	2,565.60 FL	*- FL
26	2		*REAR FENDER INNER TRIM LH/RH	Serviceable	735.40 FL	*- FL
27	2		*SETS REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	20.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*REAR FENDER SHIELD LH/RH	Not Necessary	409.68 FL	*- FL
29	2		*SETS REAR FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
30	2		*REAR FENDER TAIL LAMP LH/RH	Mtg Cracked	1,549.20 FL	*850.00 FL
31	1		*REAR FENDER TAIL LAMP PANEL LH/RH	O/S Dented / N/S Not Necessary	590.00 FL	*295.00 FL
32	1		*REAR KEYLESS ENTRY SENSOR	Mtg Broken	238.40 FL	*238.40 FL
33	1		*REAR KEYLESS ENTRY BUZZER	Mtg Bent / Cracked	229.41 FL	*229.41 FL
34	1		*REAR SPARE WHEEL PANEL	Repair	1,120.40 FL	*- FL
35	1		*REAR SPARE WHEEL PANEL TOP WOODEN BOARD	Broken	512.90 FL	*150.00 FL
36	1		*REAR SPARE WHEEL PANEL TOP TRIM	Serviceable	385.00 FL	*- FL
37	2		*REAR SPARE WHEEL SIDE PANEL LH/RH	Not Necessary	789.42 FL	*- FL
38	1		*REAR EXHAUST PIPE	Not Necessary	804.46 FL	*- FL
39	1		*REAR EXHAUST MOUNTING	Not Necessary	110.00 FL	*- FL
40	1		*REAR NUMBER PLATE & HOLDER	Not Necessary	100.00 FS	*- FS
41	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
42	1		*SET REVERSE SENSOR	Damaged	300.00 FS	*250.00 FS
43	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
45	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*SPARE WHEEL QUARTER PANEL SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*SPARE WHEEL SIDE PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,075.24	4,985.71
- List Item Discount on L Items 20.00/20.00% (\$)	3,548.65	933.14
Total Parts (\$)	15,526.59	4,052.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	1,000.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	900.00
4	TO REFIT REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	0.00
5	TO REFIT REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	60.00
6	TO CHECK REAR CHASSIS ALIGNMENT	New	200.00	0.00
7	TO REFIT EXHAUST SYSTEM AND CHECK FOR LEAKAGE	New	250.00	0.00
8	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
9	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
10	TO REFIT NEW REVERSE SENSORS ON NEW REAR BUMPER	New	200.00	40.00
11	TO REFIT NEW REVERSE CAMERA ON NEW REAR BOOT	New	200.00	0.00
12	TO APPLY ANTI-RUST COATINGS ON ALL AFFECTED AREAS	New	500.00	40.00
Gross Labour Cost (S\$)			7,400.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >