

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21007663/NVF3E2

Date: 23/03/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/21-422055-CA
Claimant Vehicle No :	SLV7690D	Insured Vehicle No :	FBP1540T
Date of Loss:	12/07/2021	Nature of Claim:	TP
		Claim No:	MSC/V/21-000327

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV7690D	Engine No:	2ZR8431141
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	ZVW506124553
Reg. Date:	15/04/2019 (Man. Year: 2018)	Odometer:	101219 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 4 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 4 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,592.92	2,798.67	9,794.25	77.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,850.00	1,160.00	6,690.00	85.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,442.92	3,958.67	16,484.25	80.64
Approved Total (Overridden) (\$\$)		1,620.00		
(\$\$)	20,442.92	1,620.00	18,822.92	92.08
+ GST 7.00/7.00% (\$\$)	1,431.00	113.40	1,317.60	92.08
Nett Amount (\$\$)	21,873.92	1,733.40	20,140.52	92.08

INSPECTION

Date of Assignment:	15/07/2021	
Date Inspected:	15/07/2021 Inspected At:	AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	4.0 days	

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV7690D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Cracked	892.00 FL	*200.00 FL
2	1		*BOOTLID WINDSCREEN MOULDING	Not Necessary	138.00 FL	*- FL
3	1		*BOOTLID LOWER WINDSCREEN WITH MOULDING	Not Necessary	458.00 FL	*- FL
4	1		*BOOTLID LOGO - TOYOTA	Necessary	49.00 FL	*49.00 FL
5	1		*BOOTLID EMBLEM - PRIUS	Not Necessary	57.00 FL	*- FL
6	1		*BOOTLID EMBLEM - HYBRID	Not Necessary	59.00 FL	*- FL
7	2		*BOOTLID NUMBER PLATE LAMP	Serviceable	128.00 FL	*- FL
8	1		*BOOTLID SWITCH	Serviceable	150.00 FL	*- FL
9	1		*BOOTLID LOCK	Serviceable	477.00 FL	*- FL
10	1		*BOOTLID LOCK COVER	Serviceable	83.00 FL	*- FL
11	1		*BOOTLID LOCK CATCH	Serviceable	25.00 FL	*- FL
12	1		*BOOTLID INNER TRIM	Cracked	521.00 FL	*300.00 FL
13	2		*BOOTLID DAMPER L+R	Serviceable	510.00 FL	*- FL
14	2		*BOOTLID STOPPER	Serviceable	38.00 FL	*- FL
15	1		*BOOTLID WEATHERSTRIP	Serviceable	322.00 FL	*- FL
16	1		*TAIL LAMP L+R	N/S Serviceable /O/S Scratched	866.00 FL	*433.00 FL
17	1		*TAIL LAMP LOWER L+R	N/S Serviceable /O/S Scratched	956.00 FL	*350.00 FL
18	1		*REAR BUMPER	Cracked	458.90 FL	*458.90 FL
19	2		*REAR BUMPER REVERSE SENSOR (NPA)	Serviceable	0.00 FL	*- FL
20	1		*REAR BUMPER LOWER	Deformed	576.00 FL	*250.00 FL
21	1		*REAR SIDE BUMPER L+R	N/S Serviceable / O/S Deformed	446.00 FL	*120.00 FL
22	2		*REAR BUMPER RETAINER L+R	Serviceable	226.00 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT BAR	Dented	319.00 FL	*319.00 FL
24	1		*REAR BUMPER SPONGE (NPA)	Serviceable	0.00 FL	*- FL
25	1		*REAR BUMPER UNDERCOVER	N/S Serviceable / O/S Deformed	442.00 FL	*150.00 FL
26	2		*REAR FENDER L+R	Serviceable	1,930.00 FL	*- FL
27	1		*REAR FENDER INNER TRIM L+R	N/S Serviceable / O/S Deformed	918.00 FL	*350.00 FL
28	2		*REAR FENDER COWLING L+R	Serviceable	172.00 FL	*- FL
29	1		*END PANEL	Repair	630.00 FL	*- FL
30	1		*END PANEL TOP GARNISH	Serviceable	195.00 FL	*- FL
31	1		*SPAREWHEEL PANEL	Serviceable	907.00 FL	*- FL
32	1		*SPAREWHEEL PANEL TOP BOARD	Serviceable	399.00 FL	*- FL
33	1		*EXHAUST PIPE	Dented	1,173.00 FL	*600.00 FL
34	1		*EXHAUST HEAT SHIELD	Serviceable	198.00 FL	*- FL
35	1		*REAR FENDER AIR VENT RH	Deformed	45.00 FL	*45.00 FL
36	1		*BOOTLID WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
37	1		*BOOTLID LOWER WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
39	1		*REAR NUMBER PLATE	Serviceable	120.00 FS	*- FS
40	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
42	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
43	1		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
44	1		*END PANEL SEALANT	Not Necessary	200.00 FS	*- FS
45	1		*END PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
46	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,283.90	3,704.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,690.98	906.23
Total Parts (\$\$)	12,592.92	2,798.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	600.00
3	TO RNR REAR WINDSCREEN	New	400.00	0.00
4	TO RNR REAR EXHAUST	New	250.00	50.00
5	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
7	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
8	TO RNR UNDERCARRIAGE	New	250.00	0.00
9	TO CHECK WATER LEAK	New	150.00	0.00
10	TO RNR FUEL TANK	New	250.00	0.00
11	TO RNR REAR BOOTLID MECHANISM	New	400.00	0.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
13	TO PERFORM RUST PROOFING	New	400.00	50.00
14	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
Gross Labour Cost (\$\$)			7,850.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >