

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21007666/GGS3Q2  
**Date:** 15/10/2021**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070099579   |
| <b>Claimant Vehicle No :</b> | SMW7204H                             | <b>Insured Vehicle No :</b> | GBG4267K     |
| Date of Loss:                | 14/07/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 9729434701SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                    |
|-----------------------------|-----------------------------------|-------------|--------------------|
| Reg No:                     | <b>SMW7204H</b>                   | Engine No:  | G4FC7U132912       |
| Make & Model:               | HYUNDAI AVANTE, 1.6 (A)           | Chassis No: | KMH DU41BR7U158421 |
| Reg. Date:                  | 12/03/2007 (Man. Year: 2007)      | Odometer:   | 119514 km          |
| Colour:                     | Blue                              |             |                    |
| Engine Capacity:            | 1591 cc                           |             |                    |
| Market Value/New Car Price: | N/A                               |             |                    |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                    |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 195/60 R15  | Rear Tyre Size:  | 195/60 R15  |
| Front Left Side:  | Falken 6 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,500.00</b>   |                   |               |

|  |             |                 |                  |
|--|-------------|-----------------|------------------|
| <b>Nett Amount (S\$)</b>                         | <b>0.00</b> | <b>2,500.00</b> | <b>-2,500.00</b> |
| <hr/>  |             |                 |                  |
| <b>+ Loss of Use (14.0 x S\$60.00/day) (S\$)</b> |             | 840.00          |                  |
| <b>+ Doc/Search Fee (S\$)</b>                    |             | 7.45            |                  |
|  |             | <hr/>           |                  |
| <b>Nett Liability (S\$)</b>                      |             | <b>3,347.45</b> |                  |
|  |             | <hr/>           |                  |
| <b>Global Sum Settlement (S\$)</b>               |             | <b>3,300.00</b> |                  |
|  |             | <hr/>           |                  |

INSPECTION

Date of Assignment: 15/07/2021

Date Inspected: 15/07/2021

Estimated Period of Repair: 0.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)  
No.1, Kaki Bukit Ave 6, #02-22 Autobay  
Singapore 417883

**Adjuster:** XING GUO QIANG**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$5,800.00

LTA REIMBURSEMENT VALUE (RV) : \$3,220.00

NETT VALUE : \$2,580.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**