

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21007669/ETF3E2

Date: 01/09/2021

REFERENCE

Insured/Claimant:	DU PENG	Policy No:	1700074608		
Date of Loss:	12/07/2021	Nature of Claim:	OD	Claim No:	5520928447SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT9094Y	Engine No:	G4FGHH678063
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFZ411MJ5740475
Reg. Date:	16/11/2017 (Man. Year: 2017)	Odometer:	82993 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,187.00	12,429.40	11,757.60	48.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,700.00	5,760.00	5,940.00	50.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	35,887.00	18,189.40	17,697.60	49.31
+ GST 7.00/7.00% (S\$)	2,512.09	1,273.26	1,238.83	49.31
Nett Amount (S\$)	38,399.09	19,462.66	18,936.43	49.31

INSPECTION

Date of Assignment:	15/07/2021	
Date Inspected:	15/07/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	13.0 days	

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRT TYRE	Crushed	370.00 FS	*370.00 FS
3	1		*SUNDRY	Repeated	20.00 FS	*- FS
4	1		*NEW K3 METAL STREAM MST	Broken	1,177.00 F	*1,177.00 F
5	1		*COVER-FR BUMPER	Broken	633.00 F	*633.00 FL
6	1		*MOULDING-FRT BPR LICENSE PLATE	Not Necessary	18.00 F	*- FL
7	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 F	*- FL
8	1		*GRILLE ASSY-RADIATOR	Broken	328.00 F	*328.00 FL
9	1		*GARNISH-RADIATOR GRILLE, UPR	Broken	54.00 F	*54.00 FL
10	1		*STRIP ASSY-FR BUMPER UPR	Torn	29.00 F	*29.00 FL
11	1		*DUCT ASSY-AIR CURTAIN, RH	Not Necessary	6.00 F	*- FL
12	1		*DUCT ASSY-AIR CURTAIN, LH	Missing	6.00 F	*6.00 FL
13	1		*MOULDING-FRONT BUMPER A/INTAKE	Broken	91.00 F	*91.00 FL
14	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	241.00 F	*- FL
15	1		*LAMP ASSY-FRONT FOG, LH	Broken	241.00 F	*241.00 FL
16	1		*ULTRASONIC SENSOR ASSY-P.A.S	Broken	177.00 F	*177.00 FL
17	1		*WIRING HARNESS-FR BUMPER	Torn	237.00 F	*237.00 FL
18	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	84.00 F	*84.00 FL
19	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 F	*- FL
20	1		*RAIL ASSY-FR BUMPER	Dented	496.00 F	*496.00 FL
21	1		*BRACKET-FR BUMPER SIDE MTG, RH	Broken	13.00 F	*13.00 FL
22	1		*BRACKET-FR BUMPER SIDE MTG, LH	Broken	13.00 F	*13.00 FL
23	1		*PANEL ASSY-HOOD	Dented	1,384.00 F	*1,384.00 FL
24	1		*PANEL-FENDER, RH	Repair	435.00 F	*- FL
25	1		*PANEL-FENDER, LH	Dented	435.00 F	*435.00 FL
26	1		*HINGE ASSY-HOOD, LH	Bent	34.00 F	*34.00 FL
27	1		*HINGE ASSY-HOOD, RH	Bent	34.00 F	*34.00 FL
28	1		*PAD-HOOD INSULATING	Torn	141.00 F	*141.00 FL
29	1		*LATCH ASSY-HOOD	Bent	65.00 F	*65.00 FL
30	1		*CARRIER ASSY-FRONT END MODULE	Dented	675.00 F	*675.00 FL
31	1		*CROSSMEMBER COMPL	Not Necessary	1,330.00 F	*- FL
32	1		*ARM COMPLETE-FR LWR, RH	Not Necessary	380.00 F	*- FL
33	1		*ARM COMPLETE-FR LWR, LH	Not Necessary	380.00 F	*- FL
34	1		*STAY RH	Not Necessary	23.00 F	*- FL
35	1		*STAY LH	Not Necessary	23.00 F	*- FL
36	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 F	*- FL
37	1		*GUARD ASSY-FRONT WHEEL, LH	Torn	95.00 F	*95.00 FL
38	1		*LAMP ASSY-HEAD, RH	Broken	2,209.00 F	*2,209.00 FL
39	1		*LAMP ASSY-HEAD, LH	Broken	2,209.00 F	*2,209.00 FL
40	1		*BUZZER ASSY-PIEZO	Not Necessary	58.00 F	*- FL
41	1		*WIRING ASSY-CONTROL	Not Necessary	2,190.00 F	*- FL
42	1		*COVER ASSY-COWL TOP	Broken	408.00 F	*408.00 FL
43	1		*COVER ASSY-COWL TOP SIDE, RH	Not Necessary	12.00 F	*- FL
44	1		*COVER ASSY-COWL TOP SIDE, LH	Not Necessary	12.00 F	*- FL
45	1		*HUB ASSY-FR WHEEL	Not Necessary	150.00 F	*- FL
46	1		*BEARING-FRONT WHEEL HUB	Not Necessary	135.00 F	*- FL
47	1		*STRUT ASSY-FR, RH	Not Necessary	313.00 F	*- FL
48	1		*STRUT ASSY-FR, LH	Not Necessary	280.00 F	*- FL
49	1		*BEARING-STRUT	Not Necessary	54.00 F	*- FL
50	1		*GUARD-AIR, RH	Not Necessary	19.00 F	*- FL
51	1		*SEAL-CONDENSER	Necessary	9.00 F	*9.00 FL
52	1		*CONDENSER ASSY-COOLER	Bent	681.00 F	*681.00 FL
53	1		*GUARD-AIR, LH	Not Necessary	19.00 F	*- FL
54	1		*RADIATOR ASSY	Dented	546.00 F	*546.00 FL
55	1		*INSULATOR-RADIATOR MTG, LWR	Not Necessary	11.00 F	*- FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*BRACKET ASSY-RADIATOR MTG, UPR	Not Necessary	21.00 F	*- FL
57	1		*BRACKET ASSY-RADIATOR MTG, UPR	Not Necessary	22.00 F	*- FL
58	1		*BLOWER ASSY	Broken	623.00 F	*623.00 FL
59	1		*HOSE ASSY-OIL COOLING	Not Necessary	70.00 F	*- FL
60	1		*HOSE ASSY-ATM OIL COOLING	Not Necessary	70.00 F	*- FL
61	1		*COVER-ENGINE UNDER FRT	Not Necessary	81.00 F	*- FL
62	1		*PANEL-SIDE COVER, RH	Not Necessary	25.00 F	*- FL
63	1		*PANEL-SIDE COVER, LH	Not Necessary	25.00 F	*- FL
64	1		*SHIELD-AIR INTAKE	Cut	10.00 F	*10.00 FL
65	1		*DUCT-AIR B	Crushed	77.00 F	*77.00 FL
66	1		*DUCT ASSY-EXTENSION	Broken	144.00 F	*144.00 FL
67	1		*CLEANER ASSY-AIR	Not Necessary	139.00 F	*- FL
68	1		*HOSE ASSY-AIR INTAKE	Not Necessary	101.00 F	*- FL
69	1		*HOSE ASSY-BREATHER	Not Necessary	28.00 F	*- FL
70	1		*MANIFOLD ASSY-INTAKE	Not Necessary	906.00 F	*- FL
71	1		*BODY ASSY-THROTTLE	Not Necessary	636.00 F	*- FL
72	1		*BRACKET-WIRING MTG	Not Necessary	2.00 F	*- FL
73	1		*SENSOR ASSY-MAP	Not Necessary	170.00 F	*- FL
74	1		*BRACKET-CONNECTOR	Not Necessary	6.00 F	*- FL
75	1		*BRACKET ASSY-TRANSMISSION MTG	Not Necessary	187.00 F	*- FL
76	1		*BRACKET ASSY-ROLL ROD	Not Necessary	180.00 F	*- FL
77	1		*FRONT RH RIM	Cut	981.00 F	*981.00 FL
78	1		*AUTO MISSION OIL (X4) (Supplementary)	Necessary	112.00 F	*112.00 FL
79	1		*COVER-VALVE BODY (Supplementary)	Broken	137.00 F	*137.00 FL
80	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 F	*26.00 FL
81	1		*RETAINER (X6) (Supplementary)	Necessary	18.00 F	*18.00 FL
82	1		*WIRING ASSY -FEM (Supplementary)	Torn	91.00 F	*91.00 FL
83	1		*ORNAMENT-KIA NO.115 (Supplementary)	Necessary	32.00 F	*32.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	24,187.00	15,145.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,715.60
Total Parts (S\$)	24,187.00	12,429.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWED FROM 517 AIR PORT RD TO P.G (NPA)	New	0.00	0.00
2	RENEW FRT BUMPER, FRT AIRDAM, BONNET, FRT SUPPORT PANEL, FRT FENDER RH & LH, REPAIR FRT DOOR RH, FRT CHASSIS RH & LH FRT WHEEL HOUSING	New	3,200.00	1,600.00
3	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
4	REMOVE & INSTALL FRT AIRDAM	New	80.00	80.00
5	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
6	SPRAY PAINT FOR FRT AIRDAM, FRT BUMPER, FRT FENDER RH & LH, BONNET, FRT CHASSIS RH & LH, FRT WHEEL HOUSING RH & LH, FRONT DOOR RH	New	3,500.00	1,750.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	FRT NUMBER PLATE WITH FRAME	New	50.00	0.00
9	TOP UP AIRCON GAS	New	80.00	80.00
10	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
11	REMOVE & INSTALL ENGINE & GEARBOX TO FACILITATE REPAIR	New	800.00	800.00
12	STRAIGHTEN FRT CHASSIS	New	500.00	0.00
13	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
14	TRANSFER FRT RIM	New	30.00	30.00
15	RENEW REAR AIRDAM, REPAIR REAR BUMPER, SIDE SKIRT RH	New	800.00	0.00
16	SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, SIDE SKIRT	New	1,200.00	0.00
17	APPLY SEALANT FOR ACCIDENT PORTION	New	80.00	40.00
18	REPAIR RH & LH FRONT CHASSIS MEMBER (Supplementary)	New	600.00	600.00
19	RESPARY RH & LH FRONT CHASSIS MEMBER (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			11,700.00	5,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >