



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
Mr Du Peng Blk 348 Woodlands Avenue 3 #11-71 Singapore 730348 Contact No Mobile: 82680279	Cust No/Name /Mr Du Peng Reg No/Reg Date SLT9094Y / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5740475 Engine No G4FGHH678063 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	15/07/2021/ 11:45	BLC	442 / CocoLu	36046
Description of Goods / Services				Qty	Unit Price Disc% Amount
M SUNDRY					20.00
Sundry					
S SPECIALISTJOB					
TOWED FROM 517 AIR PORT RD TO P.G					
(ACCIDENT)					
W/O NO:1261694					
E PNT88000	1	1	2		3200.00
RENEW FRT BUMPER, FRT AIRDAM, BONNET, FRT SUPPORT PANEL,				4 X 410	
FRT FENDER RH & LH, REPAIR FRT DOOR RH, FRT CHASSIS RH & LH					
FRT WHEEL HOUSING					
E PNT88000					100.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR					
E PNT88000					80.00
REMOVE & INSTALL FRT AIRDAM					
E PNT88000					60.00
REMOVE & INSTALL PARKING SENSOR					
E PNT98000	1	1	2		3500.00
SPRAY PAINT FOR FRT AIRDAM, FRT BUMPER, FRT FENDER RH & LH					
1 BONNET, FRT CHASSIS RH & LH, FRT WHEEL HOUSING RH & LH, FRT DOOR RH				5 X 350	
A 90000001					30.00
CHECK WIRING & ELECTRICAL SYSTEM					
M SUNDRY					50.00
FRT NUMBER PLATE WITH FRAME					
M SUNDRY					80.00
TOP UP AIRCON GAS					
A 10028901					120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
A 90000001					800.00
REMOVE & INSTALL ENGINE & GEARBOX TO FACILITATE REPAIR (photo)					
E PNT88000					500.00
STRAIGHTEN FRT CHASSIS					
B WHEELALIGNMENT					120.00
To Conduct Computerize Full Wheel Alignment					

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
Mr Du Peng Blk 348 Woodlands Avenue 3 #11-71 Singapore 730348 Contact No Mobile: 82680279	Cust No/Name /Mr Du Peng Reg No/Reg Date SLT9094Y / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5740475 Engine No G4FGHH678063 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	15/07/2021/ 11:45	BLC	442 / CocoLu	36046			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								30.00
TRANSFER FRT RIM								370.00
M SUNDRY								800.00
SUPPLY FRT TYRE (FRT RH) CRU								1200.00
E PNT88000								40 80.00
RENEW REAR AIRDAM, REPAIR REAR BUMPER, SIDE SKIRT RH (refer Video Footage)								X 20.00
E PNT98000								
SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, SIDE SKIRT (refer Video Footage)								
M SUNDRY								
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								
Sundry								
M NEW K3 METAL STREAM MST (spoiler bumper) BR					1.00	1177.00	00.00	1177.00
M COVER-FR BUMPER BR					1.00	633.00	00.00	633.00
M MOULDING-FRT BPR LICENSE PLATE X AN					1.00	18.00	00.00	18.00
M LIP ASSY-FRONT BUMPER ? X AN					1.00	55.00	00.00	55.00
M GRILLE ASSY-RADIATOR BR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE,UPR BR					1.00	54.00	00.00	54.00
M STRIP ASSY-FR BUMPER UPR ? TN					1.00	29.00	00.00	29.00
M DUCT ASSY-AIR CURTAIN,RH ? X AN					1.00	6.00	00.00	6.00
M DUCT ASSY-AIR CURTAIN,LH MIS ? BR					1.00	6.00	00.00	6.00
M MOULDING-FRONT BUMPER A/INTAKE ? BR					1.00	91.00	00.00	91.00
M LAMP ASSY-FRONT FOG,RH X AN					1.00	241.00	00.00	241.00
M LAMP ASSY-FRONT FOG,LH BR					1.00	241.00	00.00	241.00
M ULTRASONIC SENSOR ASSY-P.A.S ? BR					1.00	177.00	00.00	177.00
M WIRING HARNESS-FR BUMPER ? TN					1.00	237.00	00.00	237.00
M ABSORBER-FRONT BUMPER ENERGY BR					1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR X AN					1.00	114.00	00.00	114.00
M RAIL ASSY-FR BUMPER BR					1.00	496.00	00.00	496.00
M BRACKET-FR BUMPER SIDE MTG,RH BR					1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE MTG,LH BR					1.00	13.00	00.00	13.00
M PANEL ASSY-HOOD BR					1.00	1384.00	00.00	1384.00
M PANEL-FENDER,RH X R					1.00	435.00	00.00	435.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Du Peng Blk 348 Woodlands Avenue 3 #11-71 Singapore 730348 Contact No Mobile: 82680279	Cust No/Name / Mr Du Peng Reg No/Reg Date SLT9094Y / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5740475 Engine No G4FGHH678063 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	15/07/2021/ 11:45	BLC	442 / CocoLu	36046				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	PANEL-FENDER,LH	BT	00			1.00	435.00	00.00	435.00
M	HINGE ASSY-HOOD,LH	BT				1.00	34.00	00.00	34.00
M	HINGE ASSY-HOOD,RH	BT				1.00	34.00	00.00	34.00
M	PAD-HOOD INSULATING	BT	74			1.00	141.00	00.00	141.00
M	LATCH ASSY-HOOD	BT				1.00	65.00	00.00	65.00
M	CARRIER ASSY-FRONT END MODULE	BT	00			1.00	675.00	00.00	675.00
M	CROSSMEMBER COMPL	nn				1.00	1330.00	00.00	1330.00
M	ARM COMPLETE-FR LWR,RH	X nn				1.00	380.00	00.00	380.00
M	ARM COMPLETE-FR LWR,LH	X nn				1.00	380.00	00.00	380.00
M	STAY RH	X nn				1.00	23.00	00.00	23.00
M	STAY LH	X nn				1.00	23.00	00.00	23.00
M	GUARD ASSY-FRONT WHEEL,RH	X nn				1.00	95.00	00.00	95.00
M	GUARD ASSY-FRONT WHEEL,LH	X nn				1.00	95.00	00.00	95.00
M	LAMP ASSY-HEAD,RH	BT				1.00	2209.00	00.00	2209.00
M	LAMP ASSY-HEAD,LH	BT				1.00	2209.00	00.00	2209.00
M	BUZZER ASSY-PIEZO	X nn				1.00	58.00	00.00	58.00
M	WIRING ASSY-CONTROL	X nn				1.00	2190.00	00.00	2190.00
M	COVER ASSY-COWL TOP	BT				1.00	408.00	00.00	408.00
M	COVER ASSY-COWL TOP SIDE,RH	X nn				1.00	12.00	00.00	12.00
M	COVER ASSY-COWL TOP SIDE,LH	X nn				1.00	12.00	00.00	12.00
M	HUB ASSY-FR WHEEL	X nn				1.00	150.00	00.00	150.00
M	BEARING-FRONT WHEEL HUB	X nn				1.00	135.00	00.00	135.00
M	STRUT ASSY-FR,RH	X nn				1.00	313.00	00.00	313.00
M	STRUT ASSY-FR,LH	X nn				1.00	280.00	00.00	280.00
M	BEARING-STRUT	X nn				1.00	54.00	00.00	54.00
M	GUARD-AIR,RH	X nn				1.00	19.00	00.00	19.00
M	SEAL-CONDENSER	BT				1.00	9.00	00.00	9.00
M	CONDENSER ASSY-COOLER	BT				1.00	681.00	00.00	681.00
M	GUARD-AIR,LH	X nn				1.00	19.00	00.00	19.00
M	RADIATOR ASSY	BT				1.00	546.00	00.00	546.00
M	INSULATOR-RADIATOR MTG,LWR	X nn				1.00	11.00	00.00	11.00
M	BRACKET ASSY-RADIATOR MTG,UPR	X nn				1.00	21.00	00.00	21.00
M	BRACKET ASSY-RADIATOR MTG,UPR	X nn				1.00	22.00	00.00	22.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Du Peng Blk 348 Woodlands Avenue 3 #11-71 Singapore 730348 Contact No Mobile: 82680279	Cust No/Name /Mr Du Peng Reg No/Reg Date SLT9094Y / 16/11/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5740475 Engine No G4FGHH678063 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	15/07/2021/ 11:45	BLC	442 / CocoLu	36046			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	623.00	00.00	623.00
M BLOWER ASSY					1.00	70.00	00.00	70.00
M HOSE ASSY-OIL COOLING					1.00	70.00	00.00	70.00
M HOSE ASSY-ATM OIL COOLING					1.00	81.00	00.00	81.00
M COVER-ENGINE UNDER FRT					1.00	25.00	00.00	25.00
M PANEL-SIDE COVER,RH					1.00	25.00	00.00	25.00
M PANEL-SIDE COVER,LH					1.00	10.00	00.00	10.00
M SHIELD-AIR INTAKE					1.00	77.00	00.00	77.00
M DUCT-AIR "B"					1.00	144.00	00.00	144.00
M DUCT ASSY-EXTENSION					1.00	139.00	00.00	139.00
M CLEANER ASSY-AIR					1.00	101.00	00.00	101.00
M HOSE ASSY-AIR INTAKE					1.00	28.00	00.00	28.00
M HOSE ASSY-BREATHER					1.00	906.00	00.00	906.00
M MANIFOLD ASSY-INTAKE					1.00	636.00	00.00	636.00
M BODY ASSY-THROTTLE					1.00	2.00	00.00	2.00
M BRACKET-WIRING MTG					1.00	170.00	00.00	170.00
M SENSOR ASSY-MAP					1.00	6.00	00.00	6.00
M BRACKET-CONNECTOR					1.00	187.00	00.00	187.00
M BRACKET ASSY-TRANSMISSION MTG					1.00	180.00	00.00	180.00
M BRACKET ASSY-ROLL ROD								

Front RH Rim - CUT \$981 ✓

Steve CLKK) 00-AL AL
15/7/21, 12pm EXCESS-?
P/P
M B.L. sy
13 & dy1

LKK Auto Consultants hence notify the Repairer of the following:

* Front RH Rim - CUT \$981 ✓

Steve CLKK) OO-ML AL
15/7/21, 12:00pm EXCESS-?
P/P
M BL Sy
1/3 & dys

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

- Confirm & accepted by To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 33,540.00
7% GST on 33540.00 2347.80
Total Payable 35,887.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.