



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 6347D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WING RH REPARATION (SN)	TO REPAIR SEE LABOUR	1,557.00	-
1	WING MOULDING RH (SN)	NOT NECESSARY	234.00	-
1	INNER SIDE RH ASSY (SN)	NOT NECESSARY	2,817.00	-
1	PANEL RAIL HOUSING RH ASSY (SN)	NOT NECESSARY	108.90	-
1	RR SHOCK-ABSORB (SN)	NOT NECESSARY	153.00	-
1	RR BEARING HUB (SN)	NOT NECESSARY	198.00	-
1	FIXING BOLT M12X125 (SN)	NOT NECESSARY	4.50	-
1	PROTECTOR RHF-BRAKE DISC (SN)	NOT NECESSARY	27.00	-
1	2 DISCS KIT PRO (SN)	NOT NECESSARY	187.20	-
1	STEEL WHEEL 6.5 J16 CH5-47 (SN)	SCRATCHED	156.60	156.60
1	MONTING SCREW 12X125 (SN)	NOT NECESSARY	5.40	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			5,548.60	176.60
	<u>LABOUR</u>			
	TO CUT/REPLACE REAR RIGHT FENDER INCLUDING ALIGNMENT AND ADJUSTMENT.INCLUSIVE OF THE REPAIR OF REAR WING RH REPARATION.		3,000.00	2,400.00
	TO SPRAY PAINT ALL AFFECTED PORTIONS.		900.00	900.00
	TO CARRY OUT BODY CAVITY PRESERVATION.		60.00	60.00
	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.		60.00	60.00
	TO CONDUCT 4 WHEEL ALIGNMENT.		300.00	300.00
			4,320.00	3,720.00
GRAND TOTAL			9,868.60	3,896.60
RECOMMENDED COST OF REPAIRS				3,896.60

Report Ref No. CS/SMR21007672/R1uf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.