



CYCLE & CARRIAGE KIA PTE LTD **PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| LIM LEE KENG 83 YISHUN STREET 81 #09-04 SINGAPORE 768446 Contact No Mobile: 94523785 | Cust No/Name /LIM LEE KENG Reg No/Reg Date SMR5570P / 14/01/202 Date In/Mileage / 0 Chassis No KNAF3416ML5063037 Engine No G4FGKH739739 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | |
|--|-------|-------------------|-----|--------------|---------------|------------|-------|---------|
| CSM00081 | Cash | 15/07/2021/ 12:55 | BLC | 442 / CocoLu | 36100 | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount |
| E PNT88000 | | | | | | | | 2800.00 |
| RENEW FRT DOOR LH, REAR DOOR LH, SIDE SILL LH, WINDMIRROR LH | | | | | 5 X 420 | | | 2100 |
| 1/2 REAR BUMPER, REPAIR REAR FENDER LH | | | | | | | | 120 |
| E PNT88000 | | | | | | | | 180.00 |
| REMOVE & INSTALL FRT DOOR TRIMS AND GLASS | | | | | | | | 120 |
| E PNT88000 | | | | | | | | 180.00 |
| REMOVE & INSTALL REAR DOOR TRIMS AND GLASS | | | | | | | | 60.00 |
| E PNT88000 | | | | | | | | 60.00 |
| REMOVE & INSTALL PARKING SENSOR | | | | | | | | 2880.00 |
| E PNT98000 | | | | | | | | 2510 |
| SPRAY PAINT FOR FRT DOOR LH, REAR DOOR LH, SIDE SILL LH, REAR BUMPER | | | | | 480 X 5 + 100 | | | |
| 1 REAR FENDER LH, WINDMIRROR LH | | | | | | | | 120.00 |
| B WHEELALIGNMENT | | | | | | | | 30.00 |
| To Conduct Computerize Full Wheel Alignment | | | | | | | | 30.00 |
| A 90000001 | | | | | | | | 30.00 |
| CHECK WIRING & ELECTRICAL SYSTEM | | | | | | | | 120.00 |
| M SUNDRY | | | | | | | | 80.00 |
| TRANSFER REAR LEFT RIM | | | | | | | | 20.00 |
| A 10028901 | | | | | | | | 480.00 |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | | |
| M SUNDRY | | | | | | | | |
| APPLY SEALANT FOR ACCIDENT PORTION | | | | | | | | |
| M SUNDRY | | | | | | | | |
| Sundry | | | | | | | | |
| M SUNDRY | | | | | | | | |
| SUPPLY REAR RIM (LH) | | | | | | | | |
| M PANEL ASSY-FRONT DOOR, LH | | | | | 1.00 | 1277.00 | 00.00 | 1277.00 |
| M PANEL ASSY-REAR DOOR, LH | | | | | 1.00 | 1377.00 | 00.00 | 1377.00 |
| M PANEL-SIDE SILL OUTRER, LH | | | | | 1.00 | 1208.00 | 00.00 | 1208.00 |
| M COVER-RR BUMPER | | | | | 1.00 | 651.00 | 00.00 | 651.00 |
| M BRACKET ASSY-RR BPR SIDE UPR, L | | | | | 1.00 | 25.00 | 00.00 | 25.00 |
| M COVER-RR BUMPER FOG LAMP, LH | | | | | 1.00 | 19.00 | 00.00 | 19.00 |
| M LAMP ASSY-SIDE T/SIGNAL, LH | | | | | 1.00 | 181.00 | 00.00 | 181.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|-----------------------------|--|
| LIM LEE KENG | Cust No/Name /LIM LEE KENG |
| 83 YISHUN STREET 81 | Reg No/Reg Date SMR5570P / 14/01/202 |
| #09-04 | Date In/Mileage / 0 |
| SINGAPORE 768446 | Chassis No KNAF3416ML5063037 |
| Contact No Mobile: 94523785 | Engine No G4FGKH739739 |
| | Make/Model KIA/CERATO 1.6 A EX G333 |
| | Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|----------------------------------|-------|-------------------|------------|--------------|--------|
| CSM00081 | Cash | 15/07/2021/ 12:55 | BLC | 442 / CocoLu | 36100 |
| Description of Goods / Services | | Qty | Unit Price | Disc% | Amount |
| M COVER-RR BUMPER LWR | ✓ CUT | 1.00 | 241.00 | 00.00 | 241.00 |
| M MIRROR ASSY-OUTSIDE RR VIEW,LH | ✓ CUT | 1.00 | 559.00 | 00.00 | 559.00 |
| M MOULDING ASSY-FRT DR FRAME,LH | ✓ REC | 1.00 | 37.00 | 00.00 | 37.00 |
| M MOULDING ASSY-RR DR FRAME,LH | ✓ REC | 1.00 | 44.00 | 00.00 | 44.00 |
| M BLACK TAPE-FR DR RR,LH | ✓ REC | 1.00 | 13.00 | 00.00 | 13.00 |
| M BLACK TAPE-RR DR FR,LH | ✓ REC | 1.00 | 13.00 | 00.00 | 13.00 |
| M BLACK TAPE-RR DR FRAME RR OTR, | ✓ REC | 1.00 | 8.00 | 00.00 | 8.00 |

Estimate

ster CLKK) CD-M AL
16/7/21, 3.00pm *EXCISE -?*

P/P
my BEL sy
10 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Signature:

Date:

| | | |
|----------------------|------|------------------|
| 7% GST on | Nett | 12,633.00 |
| | | 884.31 |
| Total Payable | | 13,517.31 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.