

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21007677/GQF3E2

Date: 01/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210054366
Claimant Vehicle No : GBG4627E **Insured Vehicle No :** GBC9217T
Date of Loss: 12/07/2021 Nature of Claim: TP Claim No: 1674657819SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG4627E**
Make & Model: NISSAN NV200, 1.5 ABS AIRBAG 2WD 6DR EURO E5 W/RC (M) Engine No: K9KC400D057163
Reg. Date: 17/08/2017 (Man. Year: 2017) Chassis No: VSKYBAM20Z0145443
Colour: Grey Odometer: 56761 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/07/2021
Date Inspected: 15/07/2021 Inspected At: Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875
Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$44,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Distorted	0.00 F	*- F
3	1		*FRT BUMPER	Torn	0.00 F	*- F
4	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
5	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT LH BUMPER FOG LAMP	Cut	0.00 F	*- F
8	1		*FRT GRILLE	Cracked	0.00 F	*- F
9	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
10	2		*FRT APRON PANEL	N/S Missing / O/S Distorted	0.00 F	*- F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
13	1		*FRT WIPER BLADE	Torn	0.00 F	*- F
14	1		*WIPER PANEL GARNISH	Distorted	0.00 F	*- F
15	1		*FRT WINDSCREEN	Cracked	0.00 F	*- F
16	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
17	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
18	1		*FRT SUPPORT PANEL	Bent	0.00 F	*- F
19	1		*BONNET	Buckled	0.00 F	*- F
20	1		*BONNET LOCK	Bent	0.00 F	*- F
21	2		*BONNET HINGE	Bent	0.00 F	*- F
22	1		*BONNET RUBBER	Torn	0.00 F	*- F
23	1		*RADIATOR	Dented	0.00 F	*- F
24	1		*AIR DUCT	Cracked	0.00 F	*- F
25	1		*FRT LH FENDER	Buckled	0.00 F	*- F
26	1		*FRT LH FENDER INNER PANEL	Repair	0.00 F	*- F
27	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
28	1		*FRT LH FENDER SIGNAL LAMP	Cracked	0.00 F	*- F
29	1		*FUSE BOX	Cracked	0.00 F	*- F
30	1		*AIR CON CONDENSER	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)0.000.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >