

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007689/GVCN2**Date:** 03/12/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00084852000	
Claimant Vehicle No :	SJR3549B	Insured Vehicle No :	GBH8058R	
Date of Loss:	09/07/2021	Nature of Claim:	TP	Claim No: SNM21D203923/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR3549B		Engine No:	CAW048667
Make & Model:	VOLKSWAGEN SCIROCCO, 2.0 TSI (A)		Chassis No:	WVWZZZ13Z9V029430
Reg. Date:	19/06/2009 (Man. Year: 2009)		Odometer:	157589 km
Colour:	Grey			
Engine Capacity:	1984 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/60ZR19	Rear Tyre Size:	255/60ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,215.94	5,337.52	25,878.42	82.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,490.00	2,710.00	64.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,415.94	6,827.52	28,588.42	80.72
Approved Total (Overridden) (\$\$)		5,450.00		
(\$\$)	35,415.94	5,450.00	29,965.94	84.61
+ GST 7.00/7.00% (\$\$)	2,479.12	381.50	2,097.62	84.61
Nett Amount (\$\$)	37,895.06	5,831.50	32,063.56	84.61

INSPECTION

Date of Assignment:	16/07/2021	
Date Inspected:	15/07/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2021)
Parts:	144	VOLKSWAGEN SCIROCCO 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR3549B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,320.00 FL	*- FL
2	1		*BONNET RUBBER	Not Necessary	98.00 FL	*- FL
3	1		*FRONT BUMPER	Cracked	1,668.00 FL	*1,298.85 FL
4	2		*FRONT BUMPER SIDE RETAINER	Broken	220.00 FL	*65.10 FL
5	1		*FRONT BUMPER SPRAY NOZZLE RH	Not Necessary	379.10 FL	*- FL
6	1		*FRONT BUMPER SPRAY NOZZLE COVER	Not Necessary	67.00 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	241.70 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	950.40 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Cracked	266.10 FL	*140.95 FL
10	1		*FRONT BUMPER SUPPORT BRACKET RH	Not Necessary	112.30 FL	*- FL
11	1		*FRONT FOG LAMP GARNISH RH	Broken	287.40 FL	*164.75 FL
12	1		*FRONT FOG LAMP	Cracked	185.70 FL	*185.70 FL
13	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	457.20 FL	*- FL
14	1		*RADIATOR GRILLE	Cracked	411.00 FL	*266.95 FL
15	1		*RADIATOR GRILLE BASE	Broken	658.00 FL	*283.25 FL
16	1		*HEAD LAMP RH	Broken	1,557.40 FL	*590.60 FL
17	1		*HEAD LAMP TOP PANEL RH	Not Necessary	216.00 FL	*- FL
18	1		*FRONT SUPPORT PANEL	Cracked	1,645.70 FL	*1,140.45 FL
19	2		*FRONT SUPPORT PANEL SIDE BRACKET	Not Necessary	593.40 FL	*- FL
20	2		*FRONT SUPPORT PANEL SIDE GUARD	Not Necessary	191.00 FL	*- FL
21	2		*HORN	Not Necessary	512.40 FL	*- FL
22	1		*WINDSCREEN WASHER TANK	Cracked	404.50 FL	*130.00 FL
23	1		*WIPER TANK MOTOR 1	Cut	389.00 FL	*150.00 FL
24	1		*FRONT FENDER RH	Buckled	1,120.00 FL	*650.00 FL
25	1		*FRONT FENDER BRACKET RH	Not Necessary	108.70 FL	*- FL
26	1		*FRONT FENDER INNER SHIELD RH	Torn	330.50 FL	*186.20 FL
27	1		*FRONT LOWER ARM RH	Not Necessary	698.40 FL	*- FL
28	1		*FRONT KNUCKLE ARM RH	Not Necessary	921.50 FL	*- FL
29	1		*FRONT WHEEL BEARING RH	Not Necessary	657.00 FL	*- FL
30	1		*FRONT ANTI ROLL BAR	Not Necessary	978.00 FL	*- FL
31	1		*FRONT ANTI ROLL BAR LINK RH	Not Necessary	562.30 FL	*- FL
32	1		*FRONT DRIVE SHAFT RH	Not Necessary	2,888.40 FL	*- FL
33	1		*STEERING RACK AND PINION	Not Necessary	4,999.39 FL	*- FL
34	1		*NUMBER PLATE WITH CASING	Not Necessary	80.00 FS	*- FS
35	1		*SET FRONT BUMPER CLIP	Necessary	75.00 FS	*30.00 FS
36	1		*SET RADIATOR GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
37	1		*SET FRONT SUPPORT PANEL TOP COVER CLIP	Not Necessary	55.00 FS	*- FS
38	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	90.00 FS	*30.00 FS
39	1		*RADIATOR COOLANT	Necessary	90.00 FS	*30.00 FS
40	1		*FRONT ADJUSTABLE ABSORBER	Not Necessary	4,000.00 FS	*- FS
41	1		*FRONT RIM RH	Cut	1,500.00 FS	*500.00 FS
42	1		*FRONT TYRE RH	Not Necessary	400.00 FS	*- FS
43	1		*SIDE SKIRT RH	Not Necessary	1,400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **33,825.49** **5,862.80**
- List Item Discount on L Items 10.00/10.00% (\$\$) 2,609.55 525.28

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	31,215.94
						5,337.52
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,200.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	600.00
3	WIRING,BULB CHECKING }	New	150.00	30.00
4	REFOCUS HEADLAMP BEAM }	New	250.00	0.00
5	R&R AIRCON CONDENSOR AND REFILL AIRCON GAS }	New	200.00	100.00
6	R&R RADIATOR AND CONDUCT PRESSURE TEST }	New	200.00	0.00
7	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
8	TO REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	800.00	0.00
9	TO CHECK FOUR WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (S\$)			4,200.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >