

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007701/T1GA3Q2**Date:** 26/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800024983
Claimant Vehicle No :	SH8102U	Insured Vehicle No :	SLZ9292K
Date of Loss:	14/07/2021	Nature of Claim:	TP
		Claim No:	1079910040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8102U	Engine No:	2ZRS053883
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU903560502
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	428615 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,342.70	1,103.60	239.10	17.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	630.00	130.00	17.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,102.70	1,733.60	369.10	17.55
Approved Total (Overridden) (S\$)		1,400.00		
(S\$)	2,102.70	1,400.00	702.70	33.42
+ GST 7.00/7.00% (S\$)	147.19	98.00	49.19	33.42
Nett Amount (S\$)	2,249.89	1,498.00	751.89	33.42
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,026.20		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment:	15/07/2021		
Date Inspected:	16/07/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	499.90 FL	*499.90 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER LOWER COVER	Deformed	552.60 FL	*552.60 FL
4	1		*REAR BUMPER TOWING COVER	Deformed	82.70 FL	*82.70 FL
5	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 FL	*- FL
6	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
7	1		*REAR BUMPER REVERSE SENSOR	Not Working	135.70 FS	*135.70 FS
8	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,711.70	1,392.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	369.00	289.30
Total Parts (\$\$)	1,342.70	1,103.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
			Gross Labour Cost (\$)	760.00
				630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >