

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21007709/UBS3Q2
Date: 12/10/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001427_02
Claimant Vehicle No :	SLG9847K	Insured Vehicle No :	GBD6748S
Date of Loss:	14/07/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0003147

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG9847K	Engine No:	L15B4530714
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1810GX200713
Reg. Date:	20/10/2016 (Man. Year: 2016)	Odometer:	156106 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,458.08	1,448.56	1,009.52	41.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,690.00	1,280.00	410.00	24.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,148.08	2,728.56	1,419.52	34.22
Approved Total (Overridden) (S\$)		2,150.00		

	(S\$)	4,148.08	2,150.00	1,998.08	48.17
+ GST 7.00/7.00% (S\$)		290.37	150.50	139.87	48.17
Nett Amount (S\$)		4,438.45	2,300.50	2,137.95	48.17
+ Loss of Use (7.0 x S\$100.00/day) (S\$)			700.00		
	Nett Liability (S\$)		3,000.50		
	Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment: 21/07/2021

Date Inspected: 21/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts: M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLG9847K)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Badly Dented	960.60 FL	*935.10 FL
2	1		*REAR LH BLACK TRIM MOULDING	Distorted	47.80 FL	*47.80 FL
3	1		*REAR LH FENDER	Dented	1,063.00 FL	*655.20 FL
4	1		*REAR BUMPER	Repair	828.60 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
6	1		*REAR BUMPER SIDE	Distorted	132.60 FL	*132.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,072.60	1,810.70
- List Item Discount on L Items 20.00/20.00% (S\$)	614.52	362.14
Total Parts (S\$)	2,458.08	1,448.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TUFF COAT	New	100.00	60.00
2	TO REMOVE AND RENEW REAR PARTS	New	880.00	600.00
3	WIRING CHECK (REAR)	New	30.00	20.00
4	SPRAY PAINTING (REAR)	New	680.00	600.00
			Gross Labour Cost (\$\$)	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >