



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 889Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDEWALL FRAME (SN)	DENTED	1,512.33	1,512.33
1	PANELLING (SN)	DENTED	469.61	469.61
1	MOULDING (SN)	CUT	244.97	244.97
1	PROTECTIVE STRIP (SN) (ADDITIONAL)	CUT	67.19	67.19
1	MARKER LAMP (SN) (ADDITIONAL)	CUT	48.72	48.72
			2,342.82	2,342.82
	<u>LABOUR</u>			
	TO REMOVE & REPAIR SIDE PANEL FRONT DOOR RH.		2,700.00	2,700.00
	TO REMOVE & REFIT INNER BOX SHELF.		1,800.00	1,800.00
	LOGO.		2,250.00	800.00
	TO PUTTY & SPRAY PAINTING SIDE PANEL, FRONT DOOR AND LOWER SHIRT.		1,950.00	1,920.00
			8,700.00	7,220.00
	GRAND TOTAL		11,042.82	9,562.82
	RECOMMENDED COST OF REPAIRS			9,562.82
	LESS EXCESS			-750.00
	NETT LIABILITY			8,812.82

Report Ref No. CS/FCI21007711/Evf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.