#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21007715/GQF3E2

**Date:** 18/11/2021

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001484645

Claimant Vehicle FBS6585R Insured Vehicle No: SMS5987R

No:

Date of Loss: 09/07/2021 Nature of Claim: TP Claim No: 259884

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBS6585R

Make & Model: HONDA CBR150R, 150cc Engine No: KC92E1024507

Reg. Date: 29/06/2021 (Man. Year: 2019) Chassis No: MH1KC9217KK026803

Colour: Black Odometer: 438 km

Engine Capacity: 149 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17 Rear Tyre Size: 130/70-17
Front Left Side: IRC 6 mm Rear Left Side: IRC 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	813.80	687.60	126.20	15.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	360.00	270.00	90.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,173.80	957.60	216.20	18.42
+ GST 7.00/7.00% (S\$)	82.17	67.03	15.14	18.43
Nett Amount (S\$)	1,255.97	1,024.63	231.34	18.42

**INSPECTION** 

Date of Assignment: 16/07/2021

Everbright Motor Cycles Co (HQ)

Date Inspected: 22/07/2021 Inspected At: 53 Paya Ubi Industrial Park, #01-10/12 Ubi Avenue

1

Singapore 408934

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS \$\$44.82 NETT)

### **REPAIR DETAILS**

#### Reference

Part Source: (Last Synchronised: 18 Nov 2021)

Parts: N/A HONDA CBR150R 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBS6585R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CLUTCH LEVER	Cut	19.00 F	*19.00 FL
2	1		*LEFT FOOTREST BRACKET	* Check	49.80 F	*- FL
3	1		*LEFT MIRROR	Cut	55.00 F	*55.00 FL
4	1		*BALANCING LEFT HANDLER BAR	Cut	22.00 F	*22.00 FL
5	1		*RIGHT FRONT FAIRING	Cut	185.00 F	*185.00 FL
6	1		*RIGHT HEADLAMP	Cut	435.00 F	*435.00 FL
7	1		*LEFT SIGNAL LIGHT	Cut	48.00 F	*48.00 FL
F=Fra	anchise	part. L=ListIter	nDisc.	_		
				Sub Total (S\$)	813.80	764.00
			- List Item Discount on	L Items 0.00/10.00% (S\$)	0.00	76.40
				Total Parts (S\$)	813.80	687.60
			Report was unsubmitted du	ring this print-out		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	FORK ALIGNMENT	New	180.00	120.00
2	LABOUR	New	180.00	150.00
		Gross Labour Cost (S\$)	360.00	270.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >