



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 1880G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FAIRING (BLUE) (CONSISTENT)	CUT	300.00	50.00
2	FRONT FAIRING INNER (LH/RH)(CONSISTENT)	CRACKED	500.00	150.00
2	FRONT FAIRING LOWER (LH/RH)(CONSISTENT)	NOT NECESSARY	500.00	-
1	FRONT HEADLAMP (CONSISTENT)	CUT	350.00	195.00
1	FRONT HEADLAMP FAIRING (BLUE)(CONSISTENT)	CUT	280.00	55.00
1	FRONT HEADLAMP FAIRING (BLACK)(CONSISTENT)	CUT	250.00	50.00
2	FRONT FORK (CONSISTENT)	TO REPAIR SEE LABOUR	550.00	-
1	FRONT FORK BRACKET (CONSISTENT)	BENT	180.00	150.00
1	HANDLE BAR (CONSISTENT)	BENT	250.00	115.00
1	BRAKE LEVER (CONSISTENT)	CUT	90.00	29.00
1	BRAKE LEVER BRACKET (CONSISTENT)	NOT NECESSARY	90.00	-
1	BRAKE PEDAL (CONSISTENT)	NOT NECESSARY	90.00	-
1	FOOTREST (CONSISTENT)	CUT	90.00	45.00
1	FOOTREST RUBBER (CONSISTENT)	CUT	90.00	32.00
1	FOOTREST BRACKET (CONSISTENT)	NOT NECESSARY	110.00	-
1	PILLION FOOTREST (CONSISTENT)	CUT	90.00	45.00
1	SET BALANCER (CONSISTENT)	CUT	85.00	28.00
1	SET WING MIRROR (CONSISTENT)	CUT	150.00	50.00
1	REAR FAIRING LH (CONSISTENT)	CUT	400.00	100.00
1	FRONT FENDER (CONSISTENT)	CUT	250.00	120.00
1	SIGNAL LAMP RH (CONSISTENT)	SERVICEABLE	85.00	-
LESS 10% DISCOUNT			-478.00	-121.40
			4,302.00	1,092.60
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)(CONSISTENT)	CUT	50.00	15.00
1	IU (SN)(CONSISTENT)	CUT	156.00	156.00
1	GEAR SHAFT OIL (SN)(CONSISTENT)	NOT NECESSARY	24.00	-
1	FORK OIL SEAL (SN)(CONSISTENT)	NECESSARY	120.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FORK OIL (SN)(CONSISTENT)	NECESSARY	60.00	12.00
			410.00	213.00
	LABOUR			
	TO R&R SUSPENSION,HANDLE BAR ,HEADLAMP & FAIRING.INCLUSIVE OF THE RPAIR OF FRONT FORK .		400.00	150.00
	TO CHECK WIRING SYSTEM.}		60.00	-
	TO REMOVE & REFIT EXHAUST SILENCER. }		200.00	-
	TO SPRAY FENDER ,SIDE FAIRING AND AFFECTED AREAS .		600.00	300.00
			1,260.00	450.00
GRAND TOTAL			5,972.00	1,755.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,400.00

Report Ref No. CC4/ASM21007717/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.