

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21007718/KQF3N2**Date:** 19/11/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001622309
Claimant Vehicle No :	SMW5426Y	Insured Vehicle No :	SLN5722B
Date of Loss:	13/07/2021	Nature of Claim:	TP
		Claim No:	260004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW5426Y	Engine No:	2ZR0F66387
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800448784
Reg. Date:	26/11/2020 (Man. Year: 2020)	Odometer:	24480 km
Colour:	Metallic Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,505.35	2,314.21	11,191.14	82.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	1,375.00	3,485.00	71.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,365.35	3,689.21	14,676.14	79.91
Approved Total (Overridden) (S\$)		2,950.00		
(S\$)	18,365.35	2,950.00	15,415.35	83.94
+ GST 7.00/7.00% (S\$)	1,285.57	206.50	1,079.07	83.94
Nett Amount (S\$)	19,650.92	3,156.50	16,494.42	83.94

INSPECTION

Date of Assignment:	16/07/2021	Heng Yap Seng Auto Services - (sin Ming Drive) (HQ)
Date Inspected:	16/07/2021 Inspected At:	BLK 160 SIN MING DRIVE, #08-13 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Sep 2021)**Parts:** M1-MPV TOYOTA VOXY HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SMW5426Y)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent/Cracked	1,060.20 FL	*1,021.10 FL
2	1		*REAR BUMPER TOW HOOK COVER	Serviceable	65.15 FL	*- FL
3	2		*REAR BUMPER REFLECTORS	Serviceable	136.60 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINERS LONG	Serviceable	220.40 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINERS SHORTS	O/s Distorted	130.20 FL	*65.10 FL
6	1		*REAR BUMPER BRACKETS	Repair	55.60 FL	*- FL
7	1		*REAR BUMPER SENSOR WIRE HARDNESS	Serviceable	415.10 FL	*- FL
8	2		*REAR SIDE BUMPER	Serviceable	420.80 FL	*- FL
9	1		*TAILGATE	Bent	1,416.35 FL	*1,416.35 FL
10	1		*TAILGATE OUTER GARNISH (CHROME)	Serviceable	680.19 FL	*- FL
11	1		*TAILGATE INNER TRIM	Serviceable	690.10 FL	*- FL
12	1		*TAILGATE INNER TRIM COVER	Serviceable	292.90 FL	*- FL
13	1		*TAILGATE THIRD BRAKE LAMP	Serviceable	210.15 FL	*- FL
14	2		*TAILGATE NUMBER PLATE LAMPS	Serviceable	138.00 FL	*- FL
15	1		*TAILGATE LOGO	Necessary	74.10 FL	*74.10 FL
16	1		*TAILGATE HYBRID EMBLEM	Necessary	82.30 FL	*82.30 FL
17	1		*TAILGATE POCKET HANDLE	Serviceable	50.20 FL	*- FL
18	2		*TAILGATE STOPPER REAR	Serviceable	90.60 FL	*- FL
19	2		*TAILGATE STOPPER SIDE	Serviceable	96.30 FL	*- FL
20	1		*TAILGATE LATCH	Repair	43.10 FL	*- FL
21	2		*TAILGATE DAMPERS	Serviceable	598.90 FL	*- FL
22	2		*TAILGATE HINGES	Repair	130.20 FL	*- FL
23	1		*TAILGATE INNER LOCK	Repair	509.40 FL	*- FL
24	1		*TAILGATE DETECTOR	Serviceable	410.35 FL	*- FL
25	1		*TAILGATE SWITCH CONNECTOR	Serviceable	201.10 FL	*- FL
26	1		*TAILGATE TOP INNER TRIM	Serviceable	292.10 FL	*- FL
27	2		*TAILGATE SIDE INNER TRIM	Serviceable	420.22 FL	*- FL
28	1		*TAILGATE WEATHERSTRIP	Serviceable	399.40 FL	*- FL
29	2		*TAILGATE LOWER GARNISH RETAINERS	Serviceable	130.20 FL	*- FL
30	2		*TAILAMPS ASSY	Serviceable	1,636.80 FL	*- FL
31	2		*TAILAMPS PANELS	Repair	712.80 FL	*- FL
32	2		*TAILAMPS INNER PANEL	Repair	1,232.80 FL	*- FL
33	1		*REAR END PANEL	Repair	755.40 FL	*- FL
34	1		*REAR END PANEL TOP GARNISH	Serviceable	349.10 FL	*- FL
35	1		*REAR END PANEL EXTENSION PANEL	Repair	808.10 FL	*- FL
36	1		*REAR FLOOR PANEL	Repair	606.35 FL	*- FL
37	1		*REAR FLOOR PANEL CARPET TRIM	Serviceable	403.10 FL	*- FL
38	1		*REAR REVERSE SENSORS	Cracked	381.86 FS	*200.00 FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
40	2		*REAR BUMPER SIDE BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
41	1		*REAR NUMBER PLATE W/HOLDER	Serviceable	120.00 FS	*- FS
42	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
43	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
44	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*TAILGATE INNER SHIELD	Not Necessary	50.00 FS	*- FS
46	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
48	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
49	2		*REAR FENDER INNER TRIMS CLIPS	Not Necessary	60.00 FS	*- FS
50	1		*REAR FENDER INNER TOP TRIMS CLIPS	Not Necessary	50.00 FS	*- FS
51	2		*REAR FENDER INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
52	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
53	2		*TAILAMPS CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,496.52	2,978.95
- List Item Discount on L Items 25.00/25.00% (\$)	3,991.17	664.74
Total Parts (\$)	13,505.35	2,314.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL PARTS	New	2,000.00	500.00
2	TO RESPRAY AFFECTED AREAS	New	2,000.00	600.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	30.00
4	TO REMOVE/REFIT/REPLACE REAR REVERSE SENSORS AND DISTANCE SETTLING	New	250.00	50.00
5	TO REMOVE/REFIT REAR WINDSCREEN	New	180.00	120.00
6	TO REMOVE/REFIT AND REPLACE TAILGATE MECHANISM	New	180.00	60.00
7	TO CONDUCT WIRING CHECKS	New	100.00	15.00
			Gross Labour Cost (S\$)	1,375.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >