

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21007720/KVF3E2

Date: 29/07/2021

REFERENCE

Insured/Claimant:	ENG TIONG LEE PTE LTD	Policy No:	D19MCV0001427-02	
Date of Loss:	14/07/2021	Nature of Claim:	OD	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6748S		
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Engine No:	1KD2473787
Reg. Date:	10/03/2015 (Man. Year: 2014)	Chassis No:	JTFAT35Y30K204153
Colour:	Silver	Odometer:	134086 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$39,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 7/7 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	830.50	830.50	0.00	0.00
Miscellaneous Items	31.00	31.00	0.00	0.00
Labour	1,200.00	1,040.00	160.00	13.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,061.50	1,901.50	160.00	7.76
Approved Total (Overridden) (\$\$)		1,500.00		
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	2,061.50	900.00	1,161.50	56.34
+ GST 7.00/7.00% (\$\$)	144.31	63.00	81.31	56.34
Nett Amount (\$\$)	2,205.81	963.00	1,242.81	56.34

INSPECTION

Date of Assignment:	16/07/2021	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	16/07/2021	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Jul 2021)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD6748S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC RH HEADLAMP (WCP)	Broken	340.00 F	*340.00 F
2	1		*1 PC FRT RH CORNAL PANEL (WCP)	Bent	80.00 F	*80.00 F
3	1		*1 PC FRT RH CORNAL GARNISH (WCP)	Cut	55.00 F	*55.00 F
4	1		*1 PC FRT GRILLE (WCP)	Mtg Cracked	155.00 F	*155.00 F
5	1		*1 PC FRT GRILLE LOGO (WCP)	Necessary	35.00 F	*35.00 F
6	1		*1 PC FRT GRILLE RUBBER (WCP)	Necessary	30.00 F	*30.00 F
7	1		*1 PC FRT RH DOOR INNER FRT RUBBER (WCP)	Distorted / Cut	28.00 F	*28.00 F
8	1		*1 PC FRT PANEL EMBLEM (DYNA) (WCP)	Necessary	32.00 F	*32.00 F

F=Franchise part.

Sub Total (\$\$)	755.00	755.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	75.50	75.50
Total Parts (\$\$)	830.50	830.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 PC RH COY STICKER (NECESSARY)	20.00	20.00
2	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			31.00	31.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMP,KNOCK & REPAIR FRT RH W/SCREEN PILLAR,FRT RH DOOR & REALIGN THE SAME	New	600.00	480.00
2	PUTTY & RESPRAY ON FRT BUMPER,FRT RH DOOR,W/SCREEN PILLAR,FRT PANEL,GRILLE	New	600.00	560.00
Gross Labour Cost (\$\$)			1,200.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >