



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 7740D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT O/S DOOR OUTER PROTECTOR	DENTED	405.10	405.10
1	REAR O/S DOOR PROTECTOR	DENTED / CUT	385.70	385.70
1	REAR O/S FENDER ARCH GARNISH	DENTED	187.50	187.50
	LESS 25% DISCOUNT		-244.58	-244.58
			733.72	733.72
<u>SPECIAL NETT ITEMS</u>				
1	SET O/S ROCKER PANEL STEP GARNISH (SN)	CRACKED	2,600.00	1,900.00
30	FENDER ARCH AND ROCKER PANEL GARNISH CLIP @\$2.00 (SN)	NECESSARY	60.00	60.00
			2,660.00	1,960.00
<u>LABOUR</u>				
	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING.		500.00	200.00
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		1,000.00	600.00
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	120.00	-
	REMOVE/RENEW O/S ROCKER PANEL STEP GARNISH.		200.00	150.00
			1,820.00	950.00
GRAND TOTAL			5,213.72	3,643.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/AGI21007721/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.