



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 4929T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BENT / CRACKED	821.20	821.20
1	FRONT BUMPER LH SIDE RETAINER	DISTORTED	12.00	12.00
1	FRONT BUMPER LH FOG LAMP GARNISH	SERVICEABLE	173.10	-
6	FRONT BUMPER CLIPS @\$3.50	NECESSARY	21.00	21.00
	LESS 20% DISCOUNT		-205.46	-170.84
			821.84	683.36
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NECESSARY	30.00	30.00
			30.00	30.00
LABOUR				
	REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME.		400.00	300.00
	PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER INNER PANEL,FRT RH FENDER.		450.00	400.00
	TO APPLY,REMOVE & REFIX OPC SEAL AND SEND VEHICLE FOR INSPECTION (INCLUDING EDAY LICENCE).		80.00	80.00
			930.00	780.00
GRAND TOTAL			1,781.84	1,493.36
RECOMMENDED COST OF REPAIRS				1,493.36

Report Ref No. CS/SMR21007724/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.