

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21007725/EBS3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJP4601L	Insured Vehicle No :	SLM3518T
Date of Loss:	14/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003047

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP4601L		
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Engine No:	1ZZ3235476
Reg. Date:	25/03/2009 (Man. Year: 2009)	Chassis No:	JTDER12WX03002498
Colour:	Silver	Odometer:	390733 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Tourador 4 mm	Rear Left Side:	Tourador 4 mm
Front Right Side:	Tourador 4 mm	Rear Right Side:	Tourador 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,328.25	1,370.75	957.50	41.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	990.00	490.00	500.00	50.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,318.25	1,860.75	1,457.50	43.92
Approved Total (Overridden) (S\$)		1,500.00		

(S\$)	3,318.25	1,500.00	1,818.25	54.80
+ GST 7.00/7.00% (S\$)	232.28	105.00	127.28	54.80
Nett Amount (S\$)	3,550.53	1,605.00	1,945.53	54.80
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
Nett Liability (S\$)		2,055.00		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment: 16/07/2021

Date Inspected: 21/07/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Wah Hong Motors & Credit Pte Ltd (HQ)
 38 Toh Guan Road East, #01-57, Enterprise Hub
 Singapore 608581

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Sep 2021)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP4601L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,719.00 FL	*1,295.00 FL
2	1		*FRONT DOOR UPPER HINGE	Not Necessary	231.00 FL	*- FL
3	1		*FRONT DOOR LOWER HINGE	Not Necessary	231.00 FL	*- FL
4	1		*FRONT DOOR LOCK RH	Bent	790.00 FL	*426.00 FL
5	1		*FRONT DOOR RUBBER SEAL RH	Crushed	100.00 FS	*80.00 FS
					Sub Total (\$\$)	1,801.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	430.25
					Total Parts (\$\$)	1,370.75

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	400.00	200.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	400.00	200.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
5	TO REMOVE AND REFIX /REPLACE FRONT DOOR RH FITTING ,TRIMMINGS ,GARNISH,WINDOW GLASS AND MECHANISM	New	100.00	30.00
Gross Labour Cost (S\$)			990.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >