

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21007727/UGS3Q2
Date: 28/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549_01
Claimant Vehicle No :	SMH2404J	Insured Vehicle No :	GBJ5892H
Date of Loss:	15/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003172

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2404J		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NRX408496
Reg. Date:	16/01/2019 (Man. Year: 2018)	Chassis No:	MR2B23F3101161532
Colour:	Silver	Odometer:	25690 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,836.40	422.40	1,414.00	77.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.40	2,562.40	1,310.00	33.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,708.80	2,984.80	2,724.00	47.72
+ GST 7.00/7.00% (S\$)	399.62	208.94	190.68	47.72

Nett Amount (S\$)	6,108.42	3,193.74	2,914.68	47.72
		+ Loss of Use (4.0 x S\$50.00/day) (S\$)	200.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	3,401.19	

INSPECTION

Date of Assignment: 16/07/2021

Date Inspected: 16/08/2021

Estimated Period of Repair: 4.0 days

Inspected At: Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2021)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH2404J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*SET LED FOG LAMP (WITH GARNISH O/S)	Scratched	392.40 FS	*392.40 FS
3	1		*COVER ,FR BUMPER ,L	Repair	500.80 FS	*- FS
4	1		*RETAINER ,FR BUMPER	Not Necessary	101.60 FS	*- FS
5	10		*CLIPS	Not Necessary	41.00 FS	*- FS
6	1		*FENDER SUB -ASSY ,FR	Repair	770.60 FS	*- FS
					Total Parts (\$\$)	1,836.40
						422.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK LIGHTING & WIRING SYSTEM	New	122.40	122.40
2	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
3	REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS	New	1,800.00	1,080.00
4	RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS	New	1,770.00	1,180.00
Gross Labour Cost (\$\$)			3,872.40	2,562.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >