

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007728/T1RA3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210010752
Claimant Vehicle No :	SHD1138P	Insured Vehicle No :	SMY297A
Date of Loss:	16/07/2021	Nature of Claim:	TP
		Claim No:	3142267010SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1138P		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ096078
Reg. Date:	25/01/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ119093
Colour:	Silver	Odometer:	536635 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,126.42	337.91	3,788.51	91.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	400.00	1,050.00	72.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,576.42	737.91	4,838.51	86.77
Approved Total (Overridden) (S\$)		600.00		
(S\$)	5,576.42	600.00	4,976.42	89.24
+ GST 7.00/7.00% (S\$)	390.35	42.00	348.35	89.24
Nett Amount (S\$)	5,966.77	642.00	5,324.77	89.24
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$57.30/day) (S\$)		171.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		971.35		

INSPECTION

Date of Assignment:	16/07/2021	
Date Inspected:	26/07/2021	Inspected At: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	811.11 FL	*- FL
2	1		*FRONT O/S FENDER	Not Necessary	514.02 FL	*- FL
3	2		*FRONT BUMPER N/S & O/S SIDE BRACKET	Not Necessary	65.02 FL	*- FL
4	1		*FRONT O/S FOG LAMP	Not Necessary	840.90 FL	*- FL
5	1		*BONNET GRILLE	Not Necessary	566.46 FL	*- FL
6	1		*BONNET GRILLE -PIECE MOULDING	Cut	324.79 FL	*324.79 FL
7	1		*FRONT BUMPER EMBLEM	Not Necessary	27.80 FL	*- FL
8	1		*FRONT BUMPER TOW CAP	Cut	60.10 FL	*60.10 FL
9	1		*FRONT BUMPER LIP	Not Necessary	158.76 FL	*- FL
10	1		*FRONT O/S HEAD LAMP	Not Necessary	1,531.57 FL	*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
12	1		*FRONT N/S FENDER STICKER	Not Necessary	30.00 FS	*- FS
13	1		*SET FRONT N/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	*- FS
14	1		*FRONT NO PLATE	Not Necessary	50.00 FS	*- FS
15	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,106.53	414.89
- List Item Discount on L Items 20.00/20.00% (\$\$)					980.11	76.98
Total Parts (\$\$)					4,126.42	337.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK FRONT N/S WHEEL ALIGNMENT	New	80.00	0.00
2	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC	New	650.00	200.00
3	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,BONNET GRILLE	New	600.00	200.00
4	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,450.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >