

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007732/KPA3Q2
Date: 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800106448
Claimant Vehicle No :	SKS8035S	Insured Vehicle No :	ER7667B
Date of Loss:	15/07/2021	Nature of Claim:	TP
		Claim No:	9553086993SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS8035S	Engine No:	1AZE265477
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053BK5104010572
Reg. Date:	18/06/2013 (Man. Year: 2013)	Odometer:	126120 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,221.35	745.62	2,475.73	76.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	435.00	525.00	54.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,181.35	1,180.62	3,000.73	71.76
Approved Total (Overridden) (S\$)		950.00		
(S\$)	4,181.35	950.00	3,231.35	77.28
+ GST 7.00/7.00% (S\$)	292.69	66.50	226.19	77.28
Nett Amount (S\$)	4,474.04	1,016.50	3,457.54	77.28
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,218.50		

INSPECTION

Date of Assignment:	16/07/2021	
Date Inspected:	19/07/2021	Inspected At: City Auto Pte Ltd (Sin Ming) (HQ) Block 8 Sin Ming Road #01-58/60/62 Sin Ming Est Singapore 575643
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	596.90 FL	*522.10 FL
2	1		*FRONT BUMPER RETAINER	O/S Distorted	200.80 FL	*100.40 FL
3	1		*FRONT BUMPER SPONGE	Serviceable	102.50 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	399.50 FL	*- FL
5	1		*LH FOGLAMP	Serviceable	310.40 FL	*- FL
6	1		*LH FOGLAMP COVER	Serviceable	68.20 FL	*- FL
7	1		*WASHER TANK	Serviceable	219.10 FL	*- FL
8	1		*WASHER MOTOR	Serviceable	291.60 FL	*- FL
9	1		*LH HEADLAMP	Serviceable	1,294.60 FL	*- FL
10	1		*LH PARKING SENSOR CAP	Serviceable	20.30 FL	*- FL
11	1		*FRONT LH FENDER INNERSHIELD	Serviceable	200.10 FL	*- FL
12	8		*FRONT LH FENDER INNERSHIELD CLIP	Not Necessary	22.40 FL	*- FL
13	10		*BUMPER CLIP	Necessary	45.00 FL	*45.00 FL
14	1		*LH PARKING SENSOR	Dented	392.80 FS	*245.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,164.20	912.50
- List Item Discount on L Items 25.00/25.00% (\$)	942.85	166.88
Total Parts (\$)	3,221.35	745.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND LIGHTING	New	60.00	15.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ACCIDENT PARTS	New	400.00	200.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	500.00	220.00
			Gross Labour Cost (S\$)	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >