



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2201451

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 16/03/2022
Reference CC4/LPC21007735/Tga3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBE 6102A
Insured Veh. XD 2055Z
Claim No. 21/21/21/VC00/024773
Policy No. Z/21/VC00/109757
Accident Date 14/07/2021
Inspection Date 16/07/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21007735/Tga3q2 Date: 16/03/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 2055Z	Veh. Inspected	GBE 6102A	
Policy No.	Z/21/VC00/109757	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024773	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	16/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KDY2318022231	Colour	YELLOW	
Odometer	228343 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	GT RADIAL	6 mm	
L/H Front Tyre	195 R15	GT RADIAL	6 mm	
R/H Rear Tyre	195 R15 (D)	GT RADIAL	6/6 mm	
L/H Rear Tyre	195 R15 (D)	GT RADIAL	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/07/2021	Inspection Date	16/07/2021	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6102A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WINDSCREEN GLASS (WCP)	CRACKED	480.00	480.00
1	FRONT WINDSCREEN RUBBER (WCP)	NECESSARY	90.00	90.00
2	FRONT NOZZLE @\$35.00 (WCP)	O/S NOT NECESSARY / N/S MISSING	70.00	35.00
2	FRONT NOZZLE COVER @\$12.00 (WCP)	O/S NOT NECESSARY / N/S MISSING	24.00	12.00
1	FRONT WIPER PANEL (CENTER) (WCP)	BENT	150.00	150.00
1	FRONT WIPER SIDE PANEL N/S (WCP)	DISTORTED	60.00	60.00
1	FRONT SIDE MIRROR TRIANGLE COVER N/S (WCP)	NOT NECESSARY	75.00	-
1	FRONT SIDE MIRROR REAR COVER N/S (WCP)	NOT NECESSARY	55.00	-
1	FRONT WIPER CENTER GARNISH (WCP)	CUT	160.00	160.00
2	FRONT WIPER SIDE GARNISH @\$70.00 (WCP)	O/S NOT NECESSARY / N/S CUT	140.00	70.00
1	FRONT PANEL (WCP)	BENT	370.00	370.00
1	FRONT CORNER PANEL N/S (WCP)	TO REPAIR SEE LABOUR	125.00	-
1	FRONT CENTER GRILLE (WCP)	CRACKED	195.00	195.00
1	EMBLEM (WCP)	NOT NECESSARY	55.00	-
2	FRONT HEADLAMP @\$300.00 (WCP)	NOT NECESSARY	600.00	-
1	FRONT DASHBOARD LOWER O/S (WCP)	DEFORMED	220.00	220.00
1	FRONT DASHBOARD SIDE TOP O/S (WCP)	DEFORMED	320.00	320.00
1	FRONT DASHBOARD CENTER LOWER (WCP)	NOT NECESSARY	180.00	-
1	FRONT WIPER TANK (WCP)	CRACKED	105.00	105.00
1	FRONT WIPER TANK MOTOR (WCP)	DISTORTED	115.00	115.00
2	FRONT WIPER BLADE @\$35.00 (WCP)	O/S NOT NECESSARY / N/S BENT	70.00	35.00
2	FRONT WIPER ARM @\$80.00 (WCP)	O/S NOT NECESSARY / N/S CUT	160.00	80.00
1	FRONT WIPER LINK (WCP)	NOT NECESSARY	150.00	-
1	FRONT WIPER MOTOR (WCP)	NOT NECESSARY	250.00	-

Report Ref No. CC4/LPC21007735/Tga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON BLOWER ASSY (WCP)	CRACKED	550.00	550.00
1	COOLING COIL ASSY (WCP)	CRACKED	750.00	750.00
1	AIR CON HEATER ASSY (WCP)	CRACKED	850.00	850.00
	COST PLUS 15%		955.35	697.05
			7,324.35	5,344.05
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT ERP BRACKET (SN)	NECESSARY	15.00	15.00
			15.00	15.00
	<u>LABOUR</u>			
	TO REMOVE ,REPLACE ,REPAIR ,WELD REAR DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL N/S.		1,500.00	700.00
	TO R&R LIGHT WIRING.		60.00	30.00
	TO REMOVE & REPLACE FRONT WINDSCREEN GLASS .		120.00	120.00
	TO NUMBERING LOGO .		250.00	180.00
	TO R&R FRONT DASHBOARD .		250.00	180.00
	TO R&R AIR CON SYSTEM TO REFILL & TOP UP AIR CON GAS .		180.00	100.00
	TO PUTTY & SPRAY PAINTING .		800.00	600.00
			3,160.00	1,910.00
GRAND TOTAL			10,499.35	7,269.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CC4/LPC21007735/Tga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 6102A

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 6102A

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBE 6102A

RE-INSPECTION

