

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007737/AQCN2**Date:** 22/12/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00114492100

Claimant Vehicle No : SGC7877S **Insured Vehicle No :** SLW2003R

Date of Loss: 14/07/2021 Nature of Claim: TP Claim No: SNM21D203941/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC7877S**

Make & Model: HONDA VEZEL, 1.5 X A (A) Engine No: L15B4027962

Reg. Date: 20/01/2016 (Man. Year: 2015) Chassis No: RU11107960

Colour: Blue Odometer: 57792 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,019.84	8,748.40	16,271.44	65.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	3,330.00	3,520.00	51.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,869.84	12,078.40	19,791.44	62.10
Approved Total (Overridden) (\$\$)		9,600.00		
Nett Amount (\$\$)	31,869.84	9,600.00	22,269.84	69.88

INSPECTION

Date of Assignment: 18/07/2021

Date Inspected: 19/07/2021 Inspected At: 8 KAKI BUKIT AVENUE 4
#01-51 & 52
REPAIRER: 1ST AUTO PRO PTE LTD

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 X A (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGC7877S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Distorted	1,280.00 FL	*1,080.00 FL
2	1		*FRONT DOOR SEALANT RH	Not Necessary	180.00 FL	*- FL
3	1		*FRONT DOOR GLASS RH	Not Necessary	494.00 FL	*- FL
4	1		*FRONT DOOR TOP MOULDING RH	Not Necessary	182.00 FL	*- FL
5	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	245.00 FL	*- FL
6	1		*FRONT DOOR INNER TRIM RH	Cracked	377.00 FL	*377.00 FL
7	1		*FRONT DOOR POWER WINDOW MOTOR	Damaged	473.00 FL	*375.00 FL
8	1		*FRONT DOOR OUTER CHROME HANDLE RH	Not Necessary	352.00 FL	*- FL
9	1		*FRONT DOOR INNER LOCK RH	Damaged	310.00 FL	*310.00 FL
10	1		*FRONT DOOR LOCK STRICKER RH	Not Necessary	145.00 FL	*- FL
11	1		*FRONT DOOR BLACK TAPE RH	Necessary	172.00 FL	*172.00 FL
12	2		*FRONT DOOR HINGES RH	Not Necessary	151.20 FL	*- FL
13	1		*FRONT DOOR CHECKER RH	Not Necessary	88.60 FL	*- FL
14	1		*DOOR CENTER PILLAR RH	Repair	875.20 FL	*- FL
15	1		*DOOR REAR PILLAR RH	Not Necessary	578.50 FL	*- FL
16	1		*WING MIRROR ASSY RH	Not Necessary	856.00 FL	*- FL
17	1		*FRONT FENDER RH	Repair	660.00 FL	*- FL
18	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	251.00 FL	*- FL
19	1		*FRONT FENDER ARCH GARNISH RH	Not Necessary	310.00 FL	*- FL
20	1		*FRONT SHOCK ABSORBER RH	Not Necessary	398.40 FL	*- FL
21	1		*FRONT WHEEL HUP RH	Not Necessary	268.00 FL	*- FL
22	1		*FRONT WHEEL HUP BEARING RH	Not Necessary	264.00 FL	*- FL
23	1		*FRONT KNUCKLE ARM RH	Not Necessary	385.00 FL	*- FL
24	1		*FRONT LOWER ARM RH	Not Necessary	412.00 FL	*- FL
25	1		*FRONT ANTI ROLL BAR LINK RH	Not Necessary	158.00 FL	*- FL
26	1		*REAR DOOR RH	Distorted	1,030.00 FL	*1,030.00 FL
27	1		*REAR DOOR SEALANT RH	Not Necessary	180.00 FL	*- FL
28	1		*REAR DOOR GLASS RH	Not Necessary	494.00 FL	*- FL
29	1		*REAR DOOR TOP MOULDING RH	Not Necessary	182.00 FL	*- FL
30	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	245.00 FL	*- FL
31	1		*REAR DOOR INNER TRIM RH	Cracked	377.00 FL	*377.00 FL
32	1		*REAR DOOR POWER WINDOW MOTOR	Damaged	453.00 FL	*368.00 FL
33	1		*REAR DOOR INNER LOCK RH	Damaged	310.00 FL	*310.00 FL
34	1		*REAR DOOR LOCK STRICKER RH	Not Necessary	145.00 FL	*- FL
35	1		*REAR DOOR BLACK TAPE RH	Necessary	172.00 FL	*172.00 FL
36	2		*REAR DOOR HINGES RH	Not Necessary	151.20 FL	*- FL
37	1		*REAR DOOR CHECKER RH	Not Necessary	88.60 FL	*- FL
38	1		*ROCKER PANEL RH	Repair	660.00 FL	*- FL
39	1		*ROCKER PANEL GARNISH RH	Cut	725.00 FL	*725.00 FL
40	2		*REAR DOOR HINGES RH	Repeated	151.20 FL	*- FL
41	1		*REAR FENDER RH	Dented	760.00 FL	*760.00 FL
42	1		*REAR FENDER INNER SHIELD RH	Torn	251.00 FL	*251.00 FL
43	1		*REAR FENDER ARCH GARNISH RH	Cut	310.00 FL	*195.00 FL
44	1		*REAR SHOCK ABSORBER RH	Not Necessary	398.40 FL	*- FL
45	1		*REAR WHEEL HUP RH	Damaged	268.00 FL	*268.00 FL
46	1		*REAR WHEEL HUP BEARING RH	Not Necessary	264.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR KNUCKLE ARM RH	Not Necessary	385.00 FL	*- FL
48	1		*REAR LOWER ARM RH	Not Necessary	412.00 FL	*- FL
49	1		*REAR ANTI ROLL BAR LINK RH	Not Necessary	158.00 FL	*- FL
50	1		*ROCKER PANEL GARNISH CLIP LH	Necessary	46.20 FS	*30.00 FS
51	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
52	1		*FRONT & REAR ALLOY RIM RH (2 Pcs)	Rear Cut	1,720.00 FS	*400.00 FS
53	2		*FRONT & REAR TYRE RH	Not Necessary	500.00 FS	*- FS
54	1		*FRONT FENDER SEALANT	Not Necessary	80.00 FS	*- FS
55	1		*TYRE RIM	Not Necessary	800.00 FS	*- FS
56	1		*WHEEL TYRE	Not Necessary	280.00 FS	*- FS
57	1		*WHEEL ARCH CLIP	Necessary	55.00 FS	*20.00 FS
58	1		*DRIVER SIDE AIR BAG	Activated	1,194.00 FL	*1,194.00 FL
59	1		*DRIVER SEAT AIR BAG	Activated	994.00 FL	*994.00 FL
60	1		*FRONT PASSENGER SIDE AIR BAG	Not Necessary	1,094.00 FL	*- FL
61	1		*FRONT PASSENGER SEAT AIR BAG	Not Necessary	994.00 FL	*- FL
62	2		*REAR PASSENGER SIDE AIR NAG LH/RH	Not Necessary	2,028.00 FL	*- FL
63	1		*INNER ROOF TRIM	Crumpled	2,108.00 FL	*1,415.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,389.50	10,823.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,369.66	2,074.60
Total Parts (\$\$)	25,019.84	8,748.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT ELECTRICAL WIRING AND TEST FOR PROPER FUNCTIONING	New	350.00	30.00
2	TO REMOVE AND REFIT INNER TRIMS AND GARNISHES TO FACILITATE THE REPAIR	New	400.00	80.00
3	TO REMOVE,REALIGN AND REFIT UNDERCARRIAGE ITEMS-FRONT AND REAR	New	400.00	120.00
4	ALIGNMENT	New	200.00	80.00
5	TO TRANSFER DOOR COMPONENT FROM OLD TO NEW	New	400.00	160.00
6	TO APPLY UNDERCOATING ON REPLACED AND REPAIRED PANELS FOR RUST PROTECTION	New	100.00	80.00
7	TO PROVIDE SPRAY PAINTING ON THE REPLACED AND REPAIRED PARTS	New	2,000.00	1,000.00
8	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO ORIGINAL POSITION USING POWER TOOLS	New	2,000.00	1,200.00
9	TO REMOVE AND REFIT ROOF TRIM	New	500.00	200.00
10	TO REMOVE,REFIT AND TEST FOR AIRBAG ECU SYSTEM	New	500.00	380.00
Gross Labour Cost (\$\$)			6,850.00	3,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >