

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21007739/RGA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900167117
Claimant Vehicle No :	SG3044S	Insured Vehicle No :	SMP6762G
Date of Loss:	04/07/2021	Nature of Claim:	TP
		Claim No:	7622958050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG3044S	Engine No:	D5331345
Make & Model:	VOLVO B5LH, 5.1 D (A)	Chassis No:	YV3T1U227KA193813
Reg. Date:	11/02/2019 (Man. Year: 2018)	Odometer:	102223 km
Colour:	Green		
Engine Capacity:	5132 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,397.00	962.00	435.00	31.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,397.00	962.00	435.00	31.14
	+ Loss of Use (5.0 x S\$250.00/day) (S\$)	1,250.00		
	+ Doc/Search Fee (S\$)	7.00		
	Nett Liability (S\$)	2,219.00		
	Global Sum Settlement (S\$)	2,200.00		

INSPECTION

Date of Assignment:	16/07/2021	
Date Inspected:	16/07/2021	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	602.00	432.00
			Gross Labour Cost (\$\$)	1,397.00
				962.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >