

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007740/GQCQ2**Date:** 07/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00116892002

Claimant Vehicle No : FBE5684T **Insured Vehicle No :** GBG9461H

Date of Loss: 18/04/2021 Nature of Claim: TP Claim No: SNM21D202240/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBE5684T**

Make & Model: YAMAHA T135, 135cc Engine No: HIDDEN

Reg. Date: 07/05/2019 (Man. Year: 2019) Chassis No: 0

Colour: Blue Odometer: 0 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 70/90-17

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,444.50	729.00	715.50	49.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	150.00	580.00	79.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,174.50	879.00	1,295.50	59.58
Approved Total (Overridden) (\$\$)		700.00		
Nett Amount (\$\$)	2,174.50	700.00	1,474.50	67.81

INSPECTION

Date of Assignment: 16/07/2021

Date Inspected: 19/07/2021 Inspected At: GUSTO WORKSHOP (HQ)
25 KAKI BUKIT ROAD 4 #01-35 AYNERGY @ KB
Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2022)	
Parts:	N/A	YAMAHA T135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE5684T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR COMPLETE	Bent	120.00 FL	*120.00 FL
2	1		*BRACKET HANDLE	Bent	80.00 FL	*80.00 FL
3	1		*SET CONE BEARING	Necessary	90.00 FL	*90.00 FL
4	1		*SET MIRROR	Not Necessary	45.00 FL	*- FL
5	2		*BEARING FRONT WHEEL	Not Necessary	40.00 FL	*- FL
6	1		*SET FORK ASSY	Repair	200.00 FL	*- FL
7	1		*HEADLIGHT ASSY	Not Necessary	150.00 FL	*- FL
8	1		*SET FULL COVER	Cut	400.00 FL	*400.00 FL
9	1		*SET FOOT REST ASSY	Bent	120.00 FL	*120.00 FL
10	1		*FORK UNDER BRACKET COMPLETE	Not Necessary	100.00 FL	*- FL
11	2		*FOOT REST COVER	Not Necessary	60.00 FL	*- FL
12	1		*SET STEERING CONE & BEARING	Repeated	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,585.00	810.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	140.50	81.00
Total Parts (\$\$)	1,444.50	729.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	80.00	0.00
2	REPAIR & REBALANCE FRONT WHEEL ,ALIGN STEERING COMPONENT	New	400.00	0.00
3	RENEW DAMAGE PARTS & REPAIR AFFECTED AREAS	New	250.00	150.00
Gross Labour Cost (S\$)			730.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >