

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007742/ETCN2**Date:** 04/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00145752001
<b>Claimant Vehicle No :</b>	SGL1173G	<b>Insured Vehicle No :</b>	SMP3495Y
Date of Loss:	09/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203891/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SGL1173G</b>	Engine No:	PE20791101
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1072G0240930
Reg. Date:	24/06/2016 (Man. Year: 2016)	Odometer:	141842 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/45ZR17	Rear Tyre Size:	245/45ZR17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,151.20	1,389.50	761.70	35.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,785.00	2,070.00	1,715.00	45.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,936.20</b>	<b>3,459.50</b>	<b>2,476.70</b>	<b>41.72</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	415.53	242.17	173.36	41.72
<b>Nett Amount (\$\$)</b>	<b>6,351.73</b>	<b>3,701.67</b>	<b>2,650.06</b>	<b>41.72</b>

**INSPECTION**

Date of Assignment:	30/09/2021	
Date Inspected:	21/07/2021	Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ) 27A Tanjong Penjuru Singapore 609042
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Oct 2021)
<b>Parts:</b>	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGL1173G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,231.50 FS	*1,231.50 FS
2	1		*BRACKET CENTER RR BUMPER	Not Necessary	5.40 FS	*- FS
3	1		*REINF REAR BUMPER	Not Necessary	538.30 FS	*- FS
4	4		*GROMMET,SCREW	Necessary	12.00 FS	*12.00 FS
5	6		*FASTENER	Necessary	18.00 FS	*18.00 FS
6	1		*COVER TOWING LH	Missing	24.90 FS	*24.90 FS
7	1		*COVER TOWING RH	Missing	24.90 FS	*24.90 FS
8	1		*REFLECTOR LH	Not Necessary	53.00 FS	*- FS
9	1		*REFLECTOR RH	Not Necessary	53.00 FS	*- FS
10	1		*RETAINER LH	Not Necessary	41.00 FS	*- FS
11	1		*RETAINER RH	Not Necessary	41.00 FS	*- FS
12	1		*GASKET TAIL LAMP LH	Necessary	29.10 FS	*29.10 FS
13	1		*GASKET TAIL LAMP RH	Necessary	29.10 FS	*29.10 FS
14	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>2,151.20</b>	<b>1,389.50</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER AND REAR INFORCEMENT.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS	New	1,100.00	660.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT AND ALL AREAS AFFECTED BY THE ACCIDENTS	New	1,575.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	250.00	250.00
<b>Gross Labour Cost (\$)</b>			<b>3,785.00</b>	<b>2,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >