

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG21007746/UTF3E2

Date: 29/07/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001746272		
Claimant Vehicle No :	SGQ1984G	Insured Vehicle No :	GBG449D		
Date of Loss:	12/07/2021	Nature of Claim:	TP	Claim No:	259914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGQ1984G	Engine No:	4G18HR9090
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A7U005107
Reg. Date:	09/01/2007 (Man. Year: 2006)	Odometer:	146790 km
Colour:	Blue		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	ALTIMAX 6 mm	Rear Left Side:	ALTIMAX 6 mm
Front Right Side:	ALTIMAX 6 mm	Rear Right Side:	ALTIMAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,575.00	2,345.40	3,229.60	57.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,280.00	2,140.00	62.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,995.00	3,625.40	5,369.60	59.70
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	8,995.00	2,400.00	6,595.00	73.32
+ GST 7.00/7.00% (S\$)	629.65	168.00	461.65	73.32
Nett Amount (S\$)	9,624.65	2,568.00	7,056.65	73.32

INSPECTION

Date of Assignment:	21/07/2021		
Date Inspected:	19/07/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2021)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGQ1984G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	801.00 F	*698.00 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	65.00 F	*65.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	311.00 F	*197.00 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*HEADLAMP O/S	Broken	866.00 F	*624.00 FL
6	1		*FRONT FENDER O/S	Buckled	655.00 F	*655.00 FL
7	1		*FRONT FENDER INNER SHIELD O/S	Torn	228.00 F	*182.00 FL
8	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
9	1		*FRONT FENDER CHROME MOULDING O/S	Necessary	112.00 F	*60.00 FL
10	1		*FRONT FENDER INNER PANEL O/S	Repair	750.00 F	*- FL
11	1		*FRONT MUDFLAP O/S	Not Necessary	105.00 F	*- FL
12	1		*FRONT FENDER QUARTER GARNISH O/S	Not Necessary	55.00 F	*- FL
13	1		*FRONT FENDER SIGNAL LAMP O/S	Not Necessary	85.00 F	*- FL
14	1		*BONNET	Repair	808.00 F	*- FL
15	1		*BONNET INNER RUBBER	Torn	28.00 F	*25.00 FL
16	1		*FRONT SUPPORT PANEL	Repair	606.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,575.00	2,606.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	260.60
Total Parts (S\$)	5,575.00	2,345.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	120.00	60.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	0.00
4	TO DISMANTLE & REFIX FRT DOOR MECHANISM	New	100.00	0.00
5	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	450.00
6	TO PUTTY & SPRAY PAINTING	New	1,500.00	750.00
Gross Labour Cost (\$\$)			3,420.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >