

ASS. REC. BY: MarcusREF: CC3/MSG21007.746/443**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SGQ1984Gat Workshop m/s St.

of _____

Insured: G3G 449 D

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: £4800

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGQ1984G Yr Regn: 09/01/07Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Mit Lancer C.C. 1584Colour: blue A/C: Insured / Std / NI / NASp. Reading: 146790 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSTCS3474025107Gen. Cond: Good / Fair / Poor / BurntSteering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt orModi: Nil / Y/Rim / STD A/Rim orTyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ALTIMAXFront: 6 Rear: 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/7/21 D.O.I. 19/7/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s f.t.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Substantwe until 08-01-2022 LTA 2382net 24182/5 @ 2400

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS _____ SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$) _____)

TOTAL

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Submit to insurance.

Not Authorized
nan
19/7/21
L/S \$2400 4 days

VEHICLE No: SGQ 1984G

NETT ITEM

1PC	FRONT BUMPER	Def/torn	698.00	\$801.00
1PC	FRONT BUMPER SIDE RETAINER O/S	Bent		\$65.00
1PC	FRONT BUMPER REINFORCEMENT	Bent	197.00	\$311.00
1SET	FRONT BUMPSR CLIPS	nan		\$50.00
1PC	HEADLAMP O/S	3 no	624.00	\$866.00
1PC	FRONT FENDER O/S	Bul	677.00	\$655.00
1PC	FRONT FENDER INNER SHIELD O/S	Torn	182.00	\$228.00
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	nan		\$50.00
1PC	FRONT FENDER CHROME MOULDING O/S	nan	60.00	\$112.00
1PC	FRONT FENDER INNER PANEL O/S	R		\$750.00 X
1PC	FRONT MUDFLAP O/S	11		\$105.00 X
1PC	FRONT FENDER QUARTER GARNISH O/S	11		\$55.00 X
1PC	FRONT FENDER SIGNAL LAMP O/S	11		\$85.00 X
1PC	BONNET	R	609.00	\$808.00 X
1PC	BONNET INNER RUBBER	Torn	25.00	\$28.00
1PC	FRONT SUPPORT PANEL	R		\$606.00 X
				\$5,575.00

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX FRT DOOR MECHANISM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$120.00 60
11 \$150.00 X
11 \$100.00 X
\$1,500.00 450
\$1,500.00 750
TOTAL \$8,995.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-2606
102
P-2345.40
L-1280.00
3625.40
292
2900.