



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. MCL 5549

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT WHEEL FENDER	CUT	95.00	95.00
1	HEADLAMP	CUT	185.00	185.00
1	HEADLAMP FAIRING	CUT	195.00	195.00
1	FRONT LH SIGNAL LAMP	CRACKED	58.00	58.00
1	FRONT LH WING MIRROR	CUT	38.00	38.00
1	HANDLE GRIP LH	CUT	25.00	25.00
1	HAND LEVER LH	CUT	32.00	32.00
1	STEP BOARD LH	CUT	235.00	235.00
1	REAR LH FOOT REST	CUT	45.00	45.00
1	REAR LH FOOT REST BRACKET	NOT NECESSARY	90.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	88.00	-
1	REAR ENGINE COVER	CUT	145.00	145.00
1	REAR FAIRING LH	CUT	220.00	220.00
1	TAILLAMP LH	NOT NECESSARY	135.00	-
	LESS 10% DISCOUNT		-	-127.30
			1,586.00	1,145.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	STICKERS (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF MAIN STAND.		400.00	200.00
	SPRAY PAINTING.		400.00	200.00
	WIRING.		50.00	30.00
			850.00	430.00
	<b>GRAND TOTAL</b>		<b>2,486.00</b>	<b>1,625.70</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,000.00
---	--	--	----------

Report Ref No. CS/SMO21007747/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.