



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Balpreet Kaur Dhillon	Cust No/Name /Balpreet Kaur Dhillon
28 Jalan Gelenggang	Reg No/Reg Date SLZ4939L / 07/05/201
Singapore 578202	Date In/Mileage / 39848
Contact No Mobile: 96696319	Chassis No KNAFJ411MJ5762297
	Engine No G4FGHH692691
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	19/07/2021/ 12:01	BLE	261 / Edwin Caina	36346

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FR BUMPER, FR SUPPORT & BONNET REPAIR LHF FENDER, LHF A PILLAR, RHF FENDER & RHF A PILLAR 3.5 x 410				1400 2400.00
E PNT98000 RESPRAY FR BUMPER, BONNET, LHF FENDER, LHF A PILLAR, 4 x 359 RHF FENDER & RHF A PILLAR				1400 2100.00
E PNT88000 REMOVE & REFIT AC COND & RADIATOR				100.00
M SUNDRY TOP UP AC GAS				80.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP ATM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY SUPPLY FR NUMBER PLATE WITH CASING MIS				50.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40.00
M SUNDRY SUPPLY BODY PNL SEALANT				40.00
M SUNDRY Sundries				20.00
M COVER-FR BUMPER BR	1.00	633.00	00.00	633.00
M CAP-FRONT HOOK X	1.00	9.00	00.00	9.00
M MOULDING-FRT BPR LICENSE PLATE BR	1.00	18.00	00.00	18.00
M LIP ASSY-FRONT BUMPER CUT	1.00	55.00	00.00	55.00
M GRILLE ASSY-RADIATOR MIS	1.00	160.00	00.00	160.00
M GARNISH-RADIATOR GRILLE,UPR BR	1.00	54.00	00.00	54.00
M STRIP ASSY-FR BUMPER UPR TH	1.00	29.00	00.00	29.00
M MOULDING-FRONT BUMPER A/INTAKE ?	1.00	91.00	00.00	91.00
M DUCT ASSY-AIR CURTAIN,LH ?	1.00	6.00	00.00	6.00
M DUCT ASSY-AIR CURTAIN,RH ?	1.00	6.00	00.00	6.00
M AIR DUCT-FR BUMPER,LH ?	1.00	33.00	00.00	33.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Balpreet Kaur Dhillon	Cust No/Name /Balpreet Kaur Dhillon
28 Jalan Gelenggang	Reg No/Reg Date SLZ4939L / 07/05/201
Singapore 578202	Date In/Mileage / 39848
Contact No Mobile: 96696319	Chassis No KNAFJ411MJ5762297
	Engine No G4FGHH692691
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	19/07/2021/ 12:01	BLE	261 / Edwin Caina	36346

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M AIR DUCT-FR BUMPER,RH	1.00	33.00	00.00	33.00
M ABSORBER-FRONT BUMPER ENERGY / BR	1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR	1.00	114.00	00.00	114.00
M RAIL ASSY-FR BUMPER	1.00	496.00	00.00	496.00
M BRACKET-FR BUMPER SIDE MTG,LH	1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE MTG,RH	1.00	13.00	00.00	13.00
M PANEL ASSY-HOOD	1.00	1384.00	00.00	1384.00
M HINGE ASSY-HOOD,LH	1.00	34.00	00.00	34.00
M HINGE ASSY-HOOD,RH	1.00	34.00	00.00	34.00
M LATCH ASSY-HOOD	1.00	65.00	00.00	65.00
M LAMP ASSY-HEAD,LH	1.00	810.00	00.00	810.00
M LAMP ASSY-HEAD,RH	1.00	810.00	00.00	810.00
M ORNAMENT-KIA NO.115	1.00	32.00	00.00	32.00
M CONDENSER ASSY-COOLER	1.00	681.00	00.00	681.00
M GUARD-AIR,LH	1.00	19.00	00.00	19.00
M GUARD-AIR,RH	1.00	19.00	00.00	19.00
M RADIATOR ASSY	1.00	546.00	00.00	546.00
M FILLER NECK ASSY-RADIATOR	1.00	49.00	00.00	49.00
M BLOWER ASSY	1.00	623.00	00.00	623.00
M SHIELD-AIR INTAKE	1.00	10.00	00.00	10.00
M DUCT-AIR "B"	1.00	77.00	00.00	77.00
M DUCT ASSY-EXTENSION	1.00	144.00	00.00	144.00
M COOLANT (4L)	1.00	26.00	00.00	26.00

* from Supp read - DO SURVEYOR NAME: Steve CLKK 19/7/21, 2:00pm

SURVEYOR SIGNATURE: DO-MAL PL

DATE: EX-105-1

REMARKS: P/P, My B/L Sy
7 dgs

- Confirm & accepted by hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed

Authorized signatory and company stamp

	Nett	12,190.00
7% GST on	12190.00	853.30
Total Payable		13,043.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.