

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21007751/ETF3N2**Date:** 25/08/2021**REFERENCE**

Insured/Claimant:	TAN LAI CHOO	Policy No:	1800122936		
Date of Loss:	17/07/2021	Nature of Claim:	OD	Claim No:	2962735594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF4783L		
Make & Model:	mitsubishi OUTLANDER, 2.0 (A)	Engine No:	4J11AA7156
Reg. Date:	14/11/2018 (Man. Year: 2018)	Chassis No:	GF7W0600275
Colour:	Grey	Odometer:	47529 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,949.18	5,215.92	1,733.26	24.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,760.00	4,740.00	3,020.00	38.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,709.18	9,955.92	4,753.26	32.31
+ GST 7.00/7.00% (S\$)	1,029.64	696.91	332.73	32.32
Nett Amount (S\$)	15,738.82	10,652.83	5,085.99	32.31

INSPECTION

Date of Assignment: 19/07/2021

Date Inspected: 19/07/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-COMB RR LH	Broken	603.00 FL	*603.00 FL
2	1		*LAMP ASSY-COMB RR RH	Not Necessary	603.00 FL	*- FL
3	1		*LAMP ASSY,LICENSE PLATE (2 Pcs)	Broken (1 Pc only)	68.00 FL	*34.00 FL
4	1		*REFLECTOR,TAIL LAMP,RH	Not Necessary	100.00 FL	*- FL
5	1		*REFLECTOR,TAIL LAMP,LH	Not Necessary	100.00 FL	*- FL
6	1		*LAMP ASSY,TAIL,LH	Broken	506.00 FL	*506.00 FL
7	1		*LAMP ASSY,TAIL,RH	Cut	506.00 FL	*506.00 FL
8	1		*MOTOR,RR WINDOW WIPER	Not Necessary	505.00 FL	*- FL
9	1		*BLADE ASSY,RR WINDOW WIPER	Not Necessary	39.00 FL	*- FL
10	1		*ARM ASSY,RR WINDOW WIPER	Cut	64.00 FL	*64.00 FL
11	1		*COVER,RR WINDOW WIPER ARM	Cut	10.00 FL	*10.00 FL
12	1		*GROMMET,RR WINDOW WIPER	Necessary	8.00 FL	*8.00 FL
13	1		*BRACKET,RR WINDOW WIPER	Not Necessary	24.00 FL	*- FL
14	1		*FACE,RR BUMPER	Dented	1,018.00 FL	*811.00 FL
15	1		*REINFORCEMENT,RR BUMPER,LH	Not Necessary	79.00 FL	*- FL
16	1		*REINFORCEMENT,RR BUMPER,RH	Not Necessary	79.00 FL	*- FL
17	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	12.00 FL	*- FL
18	1		*BRKT,R/BMPR FACE SIDE,LH	Not Necessary	12.00 FL	*- FL
19	1		*EXTENSION,RR BUMPER	Dented	292.00 FL	*292.00 FL
20	1		*PANEL,RR END	Dented	326.00 FL	*326.00 FL
21	1		*PANEL ASSY,TAILGATE	Dented	989.00 FL	*989.00 FL
22	1		*W/STRIP,TAILGATE OPENING	Not Necessary	213.00 FL	*- FL
23	2		*HINGE,TAILGATE	Not Necessary	92.00 FL	*- FL
24	1		*GARNISH,TAILGATE	Broken	496.00 FL	*496.00 FL
25	4		*FASTENER,WINDSHIELD	Necessary	24.00 FL	*24.00 FL
26	1		*DAM,TAILGATE UPR	Necessary	13.00 FL	*13.00 FL
27	1		*GLASS,TAILGATE WINDOW	Broken	657.00 FL	*657.00 FL
28	2		*DAM,TAILGATE SIDE	Necessary	54.00 FL	*54.00 FL
29	2		*STOPPER,WINDSHIELD GLASS	Not Necessary	6.00 FL	*- FL
30	1		*DAM,TAILGATE LWR	Necessary	41.00 FL	*41.00 FL
31	1		*STRIKER,TAILGATE LATCH	Not Necessary	20.00 FL	*- FL
32	1		*LATCH,TAILGATE	Broken	385.00 FL	*385.00 FL
33	1		*TRIM,TAILGATE	Broken	329.00 FL	*329.00 FL
34	1		*MARK,OUTLANDER	Necessary	95.00 FL	*95.00 FL
35	1		*TRIM,RR END	Not Necessary	113.00 FL	*- FL
36	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
37	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
38	1		*BUZZER, KEYLESS OPERATIO, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
39	1		*ANT, KEYLESS OPERATION, RR (Supplementary)	Broken	96.00 FL	*96.00 FL
40	1		*MOULDING, RR BUMPER, LH (Supplementary)	Necessary	106.00 FL	*106.00 FL
41	1		*MOULDIN, RR WHEEL ARCH, LH (Supplementary)	Broken	160.00 FL	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,004.00	6,756.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,054.82	1,540.08
Total Parts (\$\$)	6,949.18	5,215.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA. REPAIR ON REAR LH FENDER & REAR FLOOR PANEL	New	3,150.00	900.00
2	PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL, REAR LH FENDER & REAR FLOOR PANEL	New	1,750.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	80.00	80.00
4	REPLACE REAR WINDSCREEN GLASS	New	240.00	240.00
5	TO APPLY WINDSCREEN GLASS	New	80.00	80.00
6	TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL	New	150.00	120.00
7	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
8	TO CLEAN OF DEBRIS OF SHATTERED GLASS	New	80.00	80.00
9	PERFORM RUST PREVENTION	New	40.00	40.00
10	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
11	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
12	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
13	TO APPLY ZERTONA COATING ON AFFECTED AREA	New	240.00	240.00
14	REPLACE REAR END PANEL, REPAIR LH REAR FENDER & REAR FLOOR PANEL (Supplementary)	New	900.00	900.00
15	RESPARY ON REAR END PANEL & REAR FLOOR PANEL (Supplementary)	New	700.00	700.00
Gross Labour Cost (\$\$)			7,760.00	4,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >