



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09690/TAN LAI CHOO Reg No/Reg Date SMF4783L / 14/11/201 Date In/Mileage 19/07/2021/ 0 Chassis No GF7W0600275 Engine No 4J11AA7156 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207


Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA REPAIR ON REAR LH FENDER & REAR FLOOR PANEL	2 X 450			900 3150.00
E PNT98000 PAINT WORK ON REAR BUMPER, TAILGATE, END PANEL, REAR LH FENDER & REAR FLOOR PANEL	3 X 350			1050 1750.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST				80.00
E PNT88000 REPLACE REAR WINDSCREEN GLASS				240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT				80.00
E PNT88000 TO TRANSFER TAILGATE ATTACHMENT TO NEW PANEL				120 150.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR (photo)				120.00
E PNT88000 TO CLEAN OF DEBRIS OF SHATTERED GLASS				80.00
M SUNDRY PERFORM RUST PREVENTION				40.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				40 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA (Provide seal again)				240.00
M SUNDRY TO SUPPLY C & C EMBLEM				40.00
M SUNDRY SUNDRIES				20 30.00
M LAMP ASSY, COMB, RR LH / BR	1.00	603.00	23.00	464.31

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691058



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENION WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09690/TAN LAI CHOO Reg No/Reg Date SMF4783L / 14/11/201 Date In/Mileage 19/07/2021/ 0 Chassis No GF7W0600275 Engine No 4J11AA7156 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LAMP ASSY, COMB, RR RH ? x AN	1.00	603.00	23.00	464.31
M LAMP ASSY, LICENSE PLATE ? BR	1.00	34.00	23.00	52.36
M REFLECTOR, TAIL LAMP, RH x (Bumper) AN	1.00	100.00	23.00	77.00
M REFLECTOR, TAIL LAMP, LH x ( " ) AN	1.00	100.00	23.00	77.00
M LAMP ASSY, TAIL, LH - BR	1.00	506.00	23.00	389.62
M LAMP ASSY, TAIL, RH ? - CUT	1.00	506.00	23.00	389.62
M MOTOR, RR WINDOW WIPER x AN AN	1.00	505.00	23.00	388.85
M BLADE ASSY, RR WINDOW WIPER x AN AN	1.00	39.00	23.00	30.03
M ARM ASSY, RR WINDOW WIPER - CUT	1.00	64.00	23.00	49.28
M COVER, RR WINDOW WIPER ARM - CUT	1.00	10.00	23.00	7.70
M GROMMET, RR WINDOW WIPER x AN	1.00	8.00	23.00	6.16
M BRACKET, RR WINDOW WIPER x AN	1.00	24.00	23.00	18.48
M FACE, RR BUMPER - DD	1.00	1018.00	23.00	783.86
M REINFORCEMENT, RR BUMPER, LH ? x AN	1.00	79.00	23.00	60.83
M REINFORCEMENT, RR BUMPER, RH ? x AN	1.00	79.00	23.00	60.83
M BRKT, R/BMPR FACE SIDE, RH ? x AN	1.00	12.00	23.00	9.24
M BRKT, R/BMPR FACE SIDE, LH ? x AN	1.00	12.00	23.00	9.24
M EXTENSION, RR BUMPER - DD	1.00	292.00	23.00	224.84
M PANEL, RR END ? - DD	1.00	326.00	23.00	251.02
M PANEL ASSY, TAILGATE - DD ? x AN	1.00	989.00	23.00	761.53
M W/STRIP, TAILGATE OPENING ? x AN	1.00	213.00	23.00	164.01
M HINGE, TAILGATE ? x AN	2.00	46.00	23.00	70.84
M GARNISH, TAILGATE - BR	1.00	496.00	23.00	381.92
P FASTENER, WINDSHIELD - APC	4.00	6.00	23.00	18.48
M DAM, TAILGATE, UPR - APC	1.00	13.00	23.00	10.01
M GLASS, TAILGATE WINDOW - BR	1.00	657.00	23.00	505.89
M DAM, TAILGATE SIDE - APC	2.00	27.00	23.00	41.58
M STOPPER, WINDSHIELD GLASS x APC AN	2.00	3.00	23.00	4.62
M DAM, TAILGATE, LWR - APC	1.00	41.00	23.00	31.57
M STRIKER, TAILGATE LATCH x AN	1.00	20.00	23.00	15.40
M LATCH, TAILGATE ? - BR	1.00	385.00	23.00	296.45
M TRIM, TAILGATE - BR	1.00	329.00	23.00	253.33
M MARK, OUTLANDER - APC	1.00	95.00	23.00	73.15

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax 65691058



Co Reg No : 1977014696

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09690/TAN LAI CHAO Reg No/Reg Date SMF4783L / 14/11/201 Date In/Mileage 19/07/2021/ 0 Chassis No GF7W0600275 Engine No 4J11AA7156 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
K4X00008	Credit	19/07/2021/ 12:36	QUK	282 / Kevin Leong	13207

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TRIM,RR END	1.00	113.00	23.00	87.01

Stere (CLKK) 00-N-1 AL  
 19/7/21, 3:30pm EXCESS - ?  
 PIP

# Estimate

8 & 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Confirm & accepted by

	Nett	12,760.37
7% GST on	12760.37	893.23
<b>Total Payable</b>		<b>13,653.60</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.