



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 17.07.2021
Emailed : 18.08.2021, 4.15pm
Date Survey : 19.07.2021

VEHICLE NO : SMF 4783 L
MODEL : MIT OUTLANDER 2.0
WIP : 13207

Table with 2 columns: Description and Amount. Rows include Material (\$5,155.92), Labour (\$4,800.00), Sub-Total (\$9,955.92), Less Excess (\$-), Total (\$9,955.92), GST 7% (\$696.91), Grand Total (\$10,652.83), and Finalise By/Date (LOI / 17/08/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of Use / Rental

[] Claim Medical Fee / Others

[] Third Party Report -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 21/07/2021	Cust No/Name	KCV09690/TAN LAI CHOO
	Reg No/Reg Date	SMF4783L / 14/11/2018
	Date In/Mileage	21/07/2021/ 47528
	Chassis/Package	GF7W0600275 /CS3P
	Engine No	4J11AA7156
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/08/2021/ 14:50	BLK	260 / AiTing	13207
Description of Goods / Services					
	Qty	Unit Price	Disc%	Amount	
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				900.00	✓
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, LH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME				1050.00	✓
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR				80.00	✓
E PNT88000 REPLACE REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST				240.00	✓
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT				80.00	✓
E PNT88000 TRANSFER TAILGATE ATTACHMENTS TO NEW PANEL				120.00	✓
E PNT88000 CLEAN DEBRIS OF SHATTERED GLASS				80.00	✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				40.00	✓
M SUNDRY APPLY SEALANT ON AFFECTED AREAS				40.00	✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00	✓
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE				120.00	✓
M SUNDRY APPLY ZERTONA COATING ON AFFECTED AREAS				240.00	✓
M SUNDRY SUPPLY C & C EMBLEM				40.00	✓
M SUNDRY SUNDRIES				20.00	✓
E PNT88000 REPLACE REAR END PANEL, REPAIR LH REAR FENDER, & REAR FLOOR PANEL				900.00	→ Supp.
E PNT88000				120.00	?

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 21/07/2021	Cust No/Name	KCV09690/TAN LAI CHOO
	Reg No/Reg Date	SMF4783L / 14/11/2018
	Date In/Mileage	21/07/2021/ 47528
	Chassis/Package	GF7W0600275 /CS3P
	Engine No	4J11AA7156
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	18/08/2021/ 14:50	BLK	260 / AiTing	13207

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
REMOVE & REINSTALL BOOT COMPARTMENT TRIMS AND ATTACHMENTS TO FACILITATE REPAIR				700.00
E PNT98000				
RESPRAY ON REAR END PANEL & REAR FLOOR PANEL → Supp				
X LAMP ASSY, COMB, RR LH	1.00	603.00	23.00	464.31
X LAMP ASSY, TAIL, LH	1.00	506.00	23.00	389.62
X LAMP ASSY, TAIL, RH	1.00	506.00	23.00	389.62
X ARM ASSY, RR WINDOW WIPER	1.00	64.00	23.00	49.28
X COVER, RR WINDOW WIPER ARM	1.00	10.00	23.00	7.70
X FACE, RR BUMPER	1.00	811.00	23.00	624.47
X EXTENSION, RR BUMPER	1.00	292.00	23.00	224.84
X PANEL, RR END	1.00	326.00	23.00	251.02
X PANEL ASSY, TAILGATE	1.00	989.00	23.00	761.53
X GARNISH, TAILGATE	1.00	496.00	23.00	381.92
X FASTENER, WINDSHIELD	4.00	6.00	23.00	18.48
X DAM, TAILGATE, UPR	1.00	13.00	23.00	10.01
X GLASS, TAILGATE WINDOW	1.00	657.00	23.00	505.89
X DAM, TAILGATE SIDE	2.00	27.00	23.00	41.58
X DAM, TAILGATE, LWR	1.00	41.00	23.00	31.57
X LATCH, TAILGATE	1.00	385.00	23.00	296.45
X TRIM, TAILGATE	1.00	329.00	23.00	253.33
X MARK, OUTLANDER	1.00	95.00	23.00	73.15
X BUZZER, KEYLESS OPERATIO, RR	1.00	91.00	23.00	70.07
X ANT, KEYLESS OPERATION, RR	1.00	96.00	23.00	73.92
X MOULDING, RR BUMPER, LH	1.00	106.00	23.00	81.62
X MOULDING, RR WHEEL ARCH, LH	1.00	160.00	23.00	123.20
X GROMMET, RR WINDOW WIPER	1.00	8.00	23.00	6.16
X LAMP ASSY, LICENSE PLATE	(2) 1.00	34.00	23.00	26.18
Z TEXT				
AIG OD CLAIM. DOA : 17.07.21 SURVEYOR STEVE LKK 19.07.21 POLICY NO : 1800122936-02 REPAIR 6D+2D = 8D <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	5,155.92	Nett	9,955.92
Labour	4,340.00	7% GST on	696.91
Standard Menu	0.00		
Specialist Job	0.00		
Diagnosics Job	0.00	Total Payable	10,652.83
Sundry/Others	460.00		
Total (w/o GST)	9,955.92		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMF 4783 L

<u>Materials</u>		<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	91.00 — BR
2	Ant, Keyless operation, RR	96.00 — BR
3	Moulding, RR bumper, LH	106.00 — NEC
4	Mouldin, RR wheel arch, LH	160.00 — BR
Total		453.00
Less 23%		104.19
Total Materials		348.81
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace rear end panel, repair LH rear fender, & rear floor panel	900.00 —
2	Respray on rear end panel, & rear floor panel	700.00 —
Total Labour		1,600.00
Taxable Amount		1,948.81
7% GST		136.42
Grand total		<u>2,085.23</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
TEL: 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMF 4783L

WIP: 13207

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Lamp Assy Tail RH sup	? / SUPP			
2	Grommet Rear Window Wiper, new	? / SUPP			
3	Panel Rear End st	? / SUPP			
4	Latch Tailgate car	? / SUPP			
5	Buzzer Rear Panel Keyless car	? / SUPP			
6	Antenna Smart Key car	? / SUPP			
7	Moulding Rear Bumper LH car	? / SUPP			
8	Moulding Rear Wheel Arch LH per	? / SUPP			
9		? / SUPP			
10	Replace Rear End Panel	? / SUPP	\$900		
11	Repair Rear LH Fender & Rear Floor	? / SUPP			
12	Respray Rear End Panel & Floor	? / SUPP	\$700	Steve	
13	R/E Rear Boot Compartment	? / SUPP	\$120	23/7/21	
14		? / SUPP			
15	Repair end panel	? / SUPP			
16	Add 2 days - Total 8 days	? / SUPP			
17	Number plate lamp x1	? / SUPP			BR Steve 27/7/21
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY

MODEL: Outlander 2.0

SURVEYOR: Steve - LKK

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETTE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBOARD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS

Reg No. SMFH788L

2021.07.29

After using PROT-3x Not work to ~~Test~~ call Test Ser

to No Test Ser

OK

to Job Done

All DTCs

Item	Setting	Information
M.U.T.-3 Version		SEW21031-00
V.C.I. Version		B179
Vehicle Information		DBA-GF7W 2019MY

All DTCs

2021.07.29

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MTTC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABSIASC/ASTCWSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	