

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007754/TPA3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700003921
Claimant Vehicle No :	SHC2375U	Insured Vehicle No :	SKK6833K
Date of Loss:	17/07/2021	Nature of Claim:	TP
		Claim No:	7598312502SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2375U		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU409555
Reg. Date:	19/12/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU190055
Colour:	Blue	Odometer:	176552 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,136.52	721.88	1,414.64	66.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,230.00	480.00	28.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,846.52	1,951.88	1,894.64	49.26
+ GST 7.00/7.00% (S\$)	269.26	136.63	132.63	49.26
Nett Amount (S\$)	4,115.78	2,088.51	2,027.27	49.26
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
(S\$)		2,964.46		
Liabe Amount (70.00%) (S\$)		2,075.12		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,077.12		
Global Sum Settlement (S\$)		2,000.00		

INSPECTION

Date of Assignment:	19/07/2021	
Date Inspected:	21/07/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Deformed	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL
4	1		*REAR BUMPER SIDE BRACKET LH	Deformed	55.80 FL	*55.80 FL
5	1		*REAR WHEEL HUB CAP LH	Cut	346.40 FL	*346.40 FL
6	1		*REAR FENDER PETROL STICKER	Necessary	15.00 FS	*15.00 FS
					Sub Total (\$)	2,666.90
					- List Item Discount on L Items 20.00/20.00% (\$)	530.38
					Total Parts (\$)	2,136.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,050.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$)			1,710.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >