

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21007760/URA3Q2
Date: 11/10/2021**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SLE5101R

Date of Loss: 13/07/2021

Policy No:

Insured Vehicle No :

SMY5558P

Nature of Claim:

TP

Claim No:

2238209161SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLE5101R**

Make & Model: HONDA VEZEL, 1.5 X (A)

Reg. Date: 25/07/2016 (Man. Year: 2015)

Colour: White

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L15B4034105

Chassis No: RU11114100

Odometer: 103987 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,437.12	715.56	4,721.56	86.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	950.00	2,250.00	70.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,637.12	1,665.56	6,971.56	80.72
Approved Total (Overridden) (S\$)		1,300.00		

Nett Amount (S\$)	8,637.12	1,300.00	7,337.12	84.95
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,807.45		

INSPECTION

Date of Assignment: 19/07/2021

Date Inspected: 19/07/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Black Eagle Auto Pte Ltd (HQ)
 25 KAKI BUKIT ROAD 4, #05-80
 Singapore 417800

Adjuster: MARCUS CHUA**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,462.00 FL	*- FL
2	1		*TAILGATE CENTRE MOULDING	Not Necessary	382.00 FL	*- FL
3	9		*TAILGATE CENTRE MOULDING CLIPS	Not Necessary	52.20 FL	*- FL
4	1		*TAILGATE INNER LOCK	Serviceable	410.00 FL	*- FL
5	2		*TAILGATE DAMPERS	Not Necessary	596.40 FL	*- FL
6	2		*TAILGATE RUBBER STOPPER	Not Necessary	11.60 FL	*- FL
7	2		*RHS & LHS TAILGATE REFLECTOR	Not Necessary	1,174.00 FL	*- FL
8	1		*REAR BOOT EDGE WEATHERSTRIP	Not Necessary	278.00 FL	*- FL
9	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	172.00 FL	*- FL
10	1		*REAR BUMPER	Dented	964.20 FL	*588.20 FL
11	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	144.00 FL	*- FL
12	2		*REAR BUMPER REFLECTORS	Not Necessary	197.00 FL	*- FL
13	1		*REAR BUMPER LOWER COVER	Not Necessary	328.00 FL	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*45.00 FS
15	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
16	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
17	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,671.40	833.20
- List Item Discount on L Items 20.00/20.00% (S\$)	1,234.28	117.64
Total Parts (S\$)	5,437.12	715.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS (INCLUDING REPAIRS AND REFIX OF ITEMS STATED IN PAGE 1)	New	1,200.00	400.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED /REPAIRED	New	1,000.00	400.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	200.00	20.00
4	TO REMOVE AND REFIX/ REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	250.00	80.00
5	TO REMOVE AND REPLACE REVERSE SENSORS AND REFIX CAMERA AND CHECK FOR PROPER FUNCTION	New	200.00	50.00
6	TO REMOVE AND REFIX TAILGATE WINDSCREEN	New	140.00	0.00
7	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	0.00
Gross Labour Cost (S\$)			3,200.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >