

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21007762/KQCN2**Date:** 20/08/2021REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00036312002
<b>Claimant Vehicle No :</b>	SGY6886G	<b>Insured Vehicle No :</b>	SKC8913S
Date of Loss:	12/07/2021	Nature of Claim:	TP
		Claim No:	SNM21D203950/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGY6886G</b>	Engine No:	H042K246B48B20A
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBAJR12010CD55352
Reg. Date:	19/03/2020 (Man. Year: 2019)	Odometer:	15697 km
Colour:	Metallic Pearl White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,577.04	4,635.57	2,941.47	38.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	1,060.00	2,640.00	71.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,277.04</b>	<b>5,695.57</b>	<b>5,581.47</b>	<b>49.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,550.00</b>		
<b>(S\$)</b>	11,277.04	4,550.00	6,727.04	59.65
<b>+ GST 7.00/7.00% (S\$)</b>	789.39	318.50	470.89	59.65
<b>Nett Amount (S\$)</b>	<b>12,066.43</b>	<b>4,868.50</b>	<b>7,197.93</b>	<b>59.65</b>

INSPECTION

Date of Assignment:	19/07/2021	
Date Inspected:	06/08/2021	Inspected At: 176 SIN MING DRIVE, SIN MING AUTOCARE #02-04 SINGAPORE 575721 REPAIRER: KGC WORKSHOP PTE LTD
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2021)
<b>Parts:</b> 143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGY6886G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,384.80 FL	*- FL
2	1		*FRONT BUMPER RETAINER RHS	Serviceable	36.80 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE RHS	Serviceable	117.00 FL	*- FL
4	1		*FRONT BUMPER LOWER GRILLE (OUTER) RHS	Serviceable	69.00 FL	*- FL
5	1		*FRONT FOG LAMP COVER	Serviceable	80.00 FL	*- FL
6	1		*FRONT FENDER RHS	Repair	938.00 FL	*- FL
7	1		*HEADLAMP ASSY RHS	Cut	4,887.60 FL	*4,879.55 FL
8	2		*FRONT PARKING SENSOR X2 (RHS)	Serviceable	410.00 FL	*- FL
9	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,973.20</b>	<b>4,879.55</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	396.16	243.98
<b>Total Parts (\$\$)</b>	<b>7,577.04</b>	<b>4,635.57</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE,REPLACE,CUT,WELD,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS,INCLUSIVE OF REPLACEMENT PARTS	New	800.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	800.00	440.00
3	TO PERFORM PAINT PROTECTION FILM (ONERPRO) AND COATING AS WELL OVER THE BUMPER AND FENDER	New	1,800.00	400.00
4	TO REMOVE AND REFIT REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	100.00	0.00
5	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	100.00	20.00
6	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,700.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >