



Your Ref : SNM21D203900/C01/TANKW

Date: 15<sup>th</sup> Dec 2021

Our Ref : CS/CTI21007765/Ktce2

**M/s China Taiping Insurance (S) Pte Ltd**

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMG 894X  
ACCIDENT ON 13/07/2021**

Instruction was received to inspect the vehicle Reg. No. SMG 894X. The inspection was conducted on 21/07/2021 at the premises of M/s S & H Motor Pte Ltd, 160 Sin Ming Drive #07-02 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number	: SMG 894X
Make/Model	: Mercedes Benz Sprinter 316CDI/3665
Year of Registration	: 2018
Body Colour	: White
Chassis Number	: WDB9066332P628123
Engine Capacity	: 2143 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Remaining Value	S\$ 75,000.00 (est)
<i>Less:</i> LTA Reimbursement Value (RV)	(S\$ 0.00
Nett Liability	<u>S\$ 0.00</u>
	=====

Vehicle Inspected By:



KONG SENG CHEONG  
*Licensed Appraiser*



K.K.LAU  
*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.