

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21007767/UQCN2**Date:** 01/10/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00002632101

Claimant Vehicle No : SMA7727G **Insured Vehicle No :** SMY844X

Date of Loss: 16/07/2021 Nature of Claim: TP **Claim No:** SNM21D203978/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA7727G**

Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB6555509

Reg. Date: 20/06/2018 (Man. Year: 2018) Chassis No: GP71212772

Colour: Blue Odometer: 50367 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,681.40	5,857.60	1,823.80	23.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	2,240.00	1,500.00	40.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,421.40	8,097.60	3,323.80	29.10
+ GST 7.00/7.00% (S\$)	799.50	566.83	232.67	29.10
Nett Amount (S\$)	12,220.90	8,664.43	3,556.47	29.10

INSPECTION

Date of Assignment: 22/07/2021

Date Inspected: 21/07/2021 Inspected At: SME Motor Pte Ltd (HQ)
1 KAKI BUKIT AVE6, #02-15
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Oct 2021)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA7727G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Distorted	988.00 FL	*988.00 FL
2	1		*FRT BUMPER RETAINER RH	Bent	19.00 FL	*19.00 FL
3	10		*FRT BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
4	1		*HEADLAMP RH	Cracked	2,227.00 FL	*2,227.00 FL
5	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	45.00 FL	*- FL
6	1		*FRT FENDER RH	Distorted	456.00 FL	*456.00 FL
7	1		*FRT FENDER HYBRID PLATE	Necessary	58.00 FL	*58.00 FL
8	1		*FRT FENDER INNER COWLING RH	Torn	145.00 FL	*145.00 FL
9	10		*INNER COWLING CLIP	Necessary	55.00 FL	*55.00 FL
10	1		*FRT RH DOOR	Distorted	792.00 FL	*792.00 FL
11	1		*FRT RH DOOR TOP HINGE	Bent	55.00 FL	*55.00 FL
12	1		*FRT RH DOOR LOWER HINGE	Bent	55.00 FL	*55.00 FL
13	1		*FRT RH DOOR CENTER STOPPER	Bent	86.00 FL	*86.00 FL
14	1		*FRT RH DOOR INNER BUMPER	Not Necessary	175.00 FL	*- FL
15	1		*FRT RH DOOR GLASS GEAR	Not Necessary	431.00 FL	*- FL
16	1		*FRT RH DOOR STICKER	Necessary	55.00 FL	*55.00 FL
17	1		*SIDE MIRROR RH	Cracked	541.00 FL	*541.00 FL
18	1		*SIDE MIRROR LOWER RH	Cracked	68.00 FL	*68.00 FL
19	1		*SIDE MIRROR SIGNAL LAMP RH	Cracked	75.00 FL	*75.00 FL
20	1		*FRT RH DOOR A PILLAR	Repair	877.00 FL	*- FL
21	1		*FRT WINDSCREEN MOULDING	Not Necessary	251.00 FL	*- FL
22	1		*FRT SHOCK ABSORBER RH	Bent	337.00 FL	*337.00 FL
23	1		*FRT SHOCK ABSORBER TOP MOUNTING RH	Not Necessary	48.00 FL	*- FL
24	1		*FRT KNUCKLE ARM RH	Bent	329.00 FL	*329.00 FL
25	1		*FRT KNUCKLE BEARING RH	Necessary	147.00 FL	*147.00 FL
26	1		*FRT LOWER ARM RH	Bent	379.00 FL	*379.00 FL
27	1		*FRT ANTO ROLL BAR LINK RH	Not Necessary	59.00 FL	*- FL
28	1		*FRT RH SPORT RIM	Cut	280.00 FS	*280.00 FS
29	1		*FRT RH TYRE	Serviceable	230.00 FS	*- FS
30	1		*FRT WINDSCREEN GUM	Not Necessary	65.00 FS	*- FS
31	1		*FRT RH DOOR SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,443.00	7,242.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,761.60	1,384.40
Total Parts (\$)	7,681.40	5,857.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX FRT WINDSCREEN	New	120.00	0.00
3	REMOVE & REFIX DASHBOARD	New	250.00	0.00
4	REMOVE & REFIX FRT UNDERCARRIAGE	New	250.00	150.00
5	WHEEL ALIGNMENT	New	80.00	80.00
6	REPLACE RIM & BALANCING	New	50.00	0.00
7	TRANSFER DOOR COMPONENT	New	100.00	60.00
8	RESET SETTINGS	New	200.00	80.00
9	TOWING	New	60.00	50.00
10	LABOUR CHARGE	New	1,400.00	800.00
11	SPRAY PAINTING	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			3,740.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >