



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 353A

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | HANDLE BAR | BENT | 45.00 | 45.00 |
| 2 | HANDLE BAR HOLDER @\$28.00 | BENT | 56.00 | 56.00 |
| 1 | SET HANDLE GRIP 'BELTA' W/BALANCER | CUT | 35.00 | 35.00 |
| 1 | CLUTCH LEVER | GRAZED | 18.00 | 18.00 |
| 1 | BRAKE LEVER | GRAZED | 18.00 | 18.00 |
| 1 | METER ASSY | CRACKED | 195.00 | 195.00 |
| 1 | METER COVER | CRACKED | 68.00 | 68.00 |
| 2 | MIRROR @\$28.00 | CRACKED / GRAZED | 56.00 | 56.00 |
| 1 | HEAD LAMP ASSY | GRAZED | 110.00 | 110.00 |
| 2 | HEAD LAMP BRACKET @\$24.00 | BENT | 48.00 | 48.00 |
| 2 | FRONT SIGNAL LAMP @\$48.00 | CRACKED / GRAZED | 96.00 | 96.00 |
| 1 | FRONT MUDGUARD | CRACKED | 48.00 | 48.00 |
| 1 | FORK TOP BRACKET | BENT | 95.00 | 95.00 |
| 2 | FRONT FORK ASSY @\$285.00 | BENT | 570.00 | 570.00 |
| 1 | STEERING EMBLEM | CRACKED | 48.00 | 48.00 |
| 1 | STEERING STEM | DISTORTED | 185.00 | 185.00 |
| 1 | FRONT WHEEL ASSY | WARPED | 250.00 | 250.00 |
| 1 | FRONT WHEEL AXLE | BENT | 20.00 | 20.00 |
| 1 | FRONT DISC BRAKE | WARPED | 185.00 | 185.00 |
| 1 | CHROME COVER (2T) LH | GRAZED | 38.00 | 38.00 |
| 1 | AIR INTAKE COVER | NOT NECESSARY | 55.00 | - |
| 1 | FUEL TANK ASSY | DENTED | 485.00 | 485.00 |
| 1 | FRONT FOOTREST LH | BENT | 45.00 | 45.00 |
| 1 | FOOTREST BRACKET LH | BENT | 65.00 | 65.00 |
| 1 | GEAR PEDAL ASSY | BENT | 45.00 | 45.00 |
| 1 | REAR FOOT PEG LH | BENT | 48.00 | 48.00 |
| 1 | REAR FOOTREST BRACKET | NOT NECESSARY | 68.00 | - |
| 1 | REAR FENDER | TO REPAIR SEE LABOUR | 145.00 | - |
| 1 | REAR MUDGUARD STAY | BENT | 55.00 | 55.00 |

Report Ref No. CS3/AGI18013456/T1f3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------|--------------|---------------------------|-------------------|
| 1 | REAR NO. PLATE LAMP | GRAZED | 45.00 | 45.00 |
| | LESS 10% DISCOUNT | | -324.00 | -297.20 |
| | | | 2,916.00 | 2,674.80 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET NUMBER PLATE (SN) | BENT | 22.00 | 22.00 |
| 1 | STEERING CONE & BEARING (SN) | NECESSARY | 55.00 | 27.50 |
| 1 | I.U UNIT (SN) | CUT / GRAZED | 156.00 | 156.00 |
| 1 | I.U BRACKET (SN) | BENT | 45.00 | 25.00 |
| | | | 278.00 | 230.50 |
| | <u>LABOUR</u> | | | |
| | TOWING FEE (4 WAYS). TRAFFIX POLICE / IDAC / REPAIR CHASSIS FRAME SPECIALIST. | | 200.00 | 120.00 |
| | CHASSIS FRAME REPAIR. | | 300.00 | 200.00 |
| | SPRAY PAINTING. | | 550.00 | 350.00 |
| | LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR FENDER. | | 500.00 | 300.00 |
| | | | 1,550.00 | 970.00 |
| | GRAND TOTAL | | 4,744.00 | 3,875.30 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,000.00 |

Report Ref No. CS3/AGI18013456/T1f3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.